



National Research  
Council  
Canada

Conseil National de  
Recherches  
Canada

Institute for Ocean  
Technology

Institut des Technologies  
Océaniques

## Ship-Iceberg Collision Incident Report



Page 1 of 3

### Vessel Characteristics

<b>Name:</b> Alcides	<b>Prime Mover:</b> Steam
<b>Flag:</b>	<b>Transmission:</b> Unknown
<b>ASPPR Ice Class:</b> Unknown	<b>Power (kW):</b> 298
<b>Lloyd's Class:</b> 1A	<b># Propellers:</b>
<b>Baltic Class:</b> Unknown	<b>Prop. Type:</b> Unknown
<b>Vessel Type:</b> Steamship	<b>Service Speed:</b>
<b>Owner:</b> Donaldson Brothers	<b>Stern Form:</b>
<b>Registered Country:</b> United Kingdom	<b>Steel Grade:</b> Unknown
<b>Year of Manufacture:</b> 1886	<b>Miscellaneous Vessel Notes:</b>
<b>Bow Shape:</b> Unknown	Steel 3 Mast Schooner
<b>Stem Angle:</b>	
<b>Dimensions (m):</b>	<b>Mass (tonnes):</b>
<b>Length:</b> 103.6	<b>Gross:</b> 3345
<b>Beam:</b> 12.8	<b>Net:</b> 2193
<b>Depth:</b> 9.1	<b>Dead:</b> 2410

### Collision Details

<b>Date:</b> 01-Jan-1890	<b>Air Temperature:</b>
<b>Visibility (nautical miles):</b>	<b>Water Temperature:</b>
<b>Visibility:</b> Unknown	<b>Wind Speed:</b>
<b>Visibility - Fog:</b> Unknown	<b>Wave Height:</b>
<b>Visibility - Snow:</b> Unknown	<b>Sea State:</b> Unknown
<b>Visibility - Light:</b> Unknown	
<b>Collision Speed:</b>	
Kerwin Place	Place Kerwin
P.O. Box 12093	C.P. 12093
St. John's, Newfoundland	St. John's, Terre-Neuve
A1B 3T5	A1B 3T5
Fax:(709) 772-2462	Télécopieur:(709) 772-2462



## Damage Details

---

<b>Damage Sustained:</b> Yes	<b>Damage Report No. :</b>
<b>Scenario:</b> Iceberg drifts upon vessel	<b>Steel Failure Type:</b> Unknown
<b>Severity:</b> Large hole	<b>Size - Length (m):</b>
<b>Location:</b> Hulls	<b>Size - Height (m):</b>
<b>Code:</b> Plate	<b>Damage Below WL (m):</b>
<b>Length of Downtime:</b>	<b>Damage Above WL - Height (m):</b>
<b>Cost of Downtime:</b>	<b>Damage Above WL - Length (m):</b>
<b>Cost to Repair:</b>	
<b>No. Lives Lost:</b>	
<b>No. Injuries:</b>	<b>Cause of Deaths/Injuries:</b> Unknown
<b>Cargo Loss:</b> Unknown	
<b>Pollution:</b> Unknown	<b>Pollution Potential:</b> Unknown

### Cause of Damage:

Struck in the side by a berg in the North Atlantic while caught in the pack ice. Lat - lon estimated.

### Damage Description:

Scored by a jagged gash that almost sank the vessel. Made St. John's.

## Ice Details

---

**Ice Briefing Received:** Unknown

**Iceberg Population:**

**IIP Iceberg Number:**

**Sea Ice Concentration:**

**Position of Nearest Known Iceberg:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown

Latitude: 0 ' " N

Iceberg Size: Unknown

Longitude: 0 ' " W

Length:

Date of Observation:

Width:

Iceberg Tonnage:

## Route Details

---

Geographic Area: Grand Banks

Origin:

Collision Latitude: 46 ° 09 ' " N

Destination:

Collision Longitude: 049 ° 09 ' " W

Distance:

Locale Accuracy: Unknown

Cargo at Event:

Voyage:

Displacement:

Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

