National Research

Council Canada Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

# Ship-Iceberg Collision Incident Report

1856

Mass (tonnes):

Gross:

Net:

Dead:

1

Page 1

## **Vessel Characteristics**

Name: Alert Flag: U.S.A.

ASPPR Ice Class: Unknown

Lloyd's Class: Unknown

**Baltic Class:** Unknown

Sailing Vessel - Power Assisted **Vessel Type:** Owner: Royal Navy

UK **Registered Country:** 

Year of Manufacture:

Bow Shape: Unknown

Stem Angle:

Dimensions (m):

Length:

Beam:

Depth:

Prime Mover:

Transmission:

Unknown

Steam

Power (kW):

# Propellers:

Prop. Type: Unknown

Service Speed:

Stern Form:

751

Steel Grade:

Unknown

**Miscellaneous Vessel Notes:** HMS. A screw driven sloop.

C.1884 donated to the U.S. as a relief ship for

Greely's Arctic Expedition.

### **Collision Details**

Date: 01-Aug-1884

Visibility: Limited Visibility - Fog:

**Collision Speed:** 

Visibility (nautical miles):

Unknown

Visibility - Snow: Snow

Visibility - Light:

Unknown

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Terre-Neuve St. John's, Newfoundland A1B 3T5

A1B 3T5 Télécopieur: (709) 772-2462

Fax:(709) 772-2462

Air Temperature:

WaterTemperature:

Wind Speed:

WaveHeight:

Sea State: Unknown



## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: No Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: No damage Size - Length (m):

Location: Unknown Size - Height (m):

Code: Unknown Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Struck in hazy conditions from falling snow struck a berg at 9 knots presumable somewhere in Baffin Bay. Lat - lon estimated.

#### **Damage Description:**

Almost knocked the lookout from the crows nest but not a seam started.

## Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Baffin Bay Area

Collision Latitude: 73 ° 00 ' " N

Collision Longitude: 065 ° 00 ' " W

Locale Accuracy: Estimated

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: USA

**Destination:** Kane Basin, Arctic

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

