National Research Council

Council Canada

Institute for Ocean Institut des Technologies Technology Océaniques

Conseil National de

Recherches

Canada

Ship-Iceberg Collision Incident Report

NAC CNAC

Page 1 of 3

**Vessel Characteristics** 

Name:AnerleyPrime Mover:SteamFlag:UKTransmission:Unknown

ASPPR Ice Class: Unknown Power (kW):
Lloyd's Class: Unknown # Propellers:

Baltic Class: Unknown Prop. Type: Unknown

 Vessel Type:
 Steamship
 Service Speed:

 Owner:
 Stern Form:

Registered Country: Steel Grade: Unknown
Year of Manufacture: Miscellaneous Vessel Notes:

0

Bow Shape: Unknown Of London.

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

Length: Gross:
Beam: Net:

Depth: Dead:

**Collision Details** 

Date: 30-Nov-1884

Visibility (nautical miles): Air Temperature:

Visibility: Limited WaterTemperature:

Visibility - Fog:UnknownWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Night Sea State: Rough

**Collision Speed:** 

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canada

## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Striking projection Steel Failure Type: Unknown

Severity: Puncture Size - Length (m):

Location: Hulls Size - Height (m):

Code: Plate Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Heavily laden and in very stormy conditions between Fogo Island and Snap Rock about 80 miles off the coast trying to avoid iceberg in the dark at 6 a.m. hard to port, wave lifted lifted steamer and dumped her hard on underwater projection.

#### **Damage Description:**

Made to launch the lifeboats but were dashed to pieces. Sounded the bilges and found that ship was leaking at 2' (0.6 m) per hour. Pumps kept going continuously until reached New York. Lucky escape for no boat could have survived those seas. Shock of impact produced a stowaway from the bunkers who had to work for the rest of the passage.

#### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Grand Banks

Collision Latitude:  $49 \, ^{\circ} \, 47 \, '$  " N

Collision Longitude: 053 ° 56 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: Bett's Cove, NF

Destination: New York

Distance:

Cargo at Event: 2,100 tons of copper ore.

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

