National Research Council

Council Canada

Institute for Ocean Technology

Conseil National de

Recherches Canada

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Asquith Prime Mover: Sail

Flag: Transmission: Unknown

ASPPR Ice Class: Unknown Power (kW):
Lloyd's Class: Unknown # Propellers:

Baltic Class: Unknown Prop. Type: Unknown

 Vessel Type:
 Sailing Vessel
 Service Speed:

 Owner:
 A.E. Hickman Company Limited
 Stern Form:

Registered Country: Canada Steel Grade: Unknown

Year of Manufacture: 1916 <u>Miscellaneous Vessel Notes:</u>

Bow Shape: Unknown Wooden 3 mast schooner.

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

 Length:
 38.5
 Gross:
 323

 Beam:
 9.6
 Net:
 271

 Depth:
 3.5
 Dead:
 261

Collision Details

Visibility (nautical miles):

Date: 01-Aug-1919

Visibility: Unknown WaterTemperature:

Air Temperature:

Visibility - Fog:UnknownWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Unknown Sea State: Unknown

Collision Speed:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

| Damage Sustained: Yes | Damage Report No. : |
|-----------------------|---------------------|
|-----------------------|---------------------|

Scenario: Glancing Blow Steel Failure Type: Unknown

Severity: Crushed Size - Length (m):

Location: Bow Size - Height (m):

Code: Appendage Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: No

Pollution: No Pollution Potential: No

Cause of Damage:

Hit a berg in the North Atlantic sailing from Cadiz June 25 arriving St. John's August 8.

Damage Description:

Lost headgear.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: 46 $^{\circ}$ 06 $^{\prime}$ " N

Collision Longitude: 048 ° 42 ' " W

Locale Accuracy: Unknown

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Cadiz

Destination: St. John's

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

