

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

Name: Brooklyn C	lame: Brooklyn City		Pri	me Mover:	Steam
Flag: UK			Tra	nsmission:	Unknown
ASPPR Ice Class:	Unknown		Ρο	wer (kW):	
Lloyd's Class:	Unknown		# P	ropellers:	
Baltic Class:	Unknown		Pro	p. Type:	Unknown
Vessel Type:	Steamship		Ser	vice Speed	:
Owner: Bristol City Line		Ste	Stern Form:		
Registered Country:			Ste	el Grade:	Unknown
Year of Manufacture:			Miscellaneous Vessel Notes:		
Bow Shape: Unknown			In service with Bristol City Line 1881 - 1910, sold and renamed "Gibilterra".		
Stem Angle:				sold and r	enamed "Gibliterra".
<u>Dimensions (m):</u> Length: Beam: Depth:	Mass	<u>(tonnes):</u> Gross: 17 Net: Dead:	25 0		

## **Collision Details**

Date: 01-Apr-1897				
Visibility (nautical miles):		Air Temperature:		
Visibility: Poor		WaterTemperature:		
Visibility - Fog: Fog		Wind Speed:		
Visibility - Snow: Unknown		WaveHeight:		
Visibility - Light: Night		Sea State: Unknown		
Collision Speed:	4			
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä	

## Ship-Iceberg Collision Incident Report



## **Damage Details**

Damage Sustained: Yes	Damage Report No. :			
Scenario: Striking projection	Steel Failure Type: Unknown			
Severity: Hole	Size - Length (m):			
Location: Hull and tanks	Size - Height (m):			
Code: Plate	Damage Below WL (m):			
Length of Downtime:	Damage Above WL - Height (m):			
Cost of Downtime:	Damage Above WL - Length (m):			
Cost to Repair:				
No. Lives Lost:				
No. Injuries:	Cause of Deaths/Injuries: Unknown			
Cargo Loss: Unknown				
Pollution: Unknown	Pollution Potential: Unknown			

#### Cause of Damage:

After clearing field ice into a lead an iceberg loomed ahead in the fog. Wheel thrown hard over and appeared was going to miss when vessel when bow raised up then ship slid to side with much grinding noise. Berg was 60' (18 m) high or more and about 100' (30 m) long and struck at 11:45 p.m just off the Grand Banks.

#### **Damage Description:**

Plates intact above the waterline but water fooded forepeak to a depth of 15' (4.5 m). The watertight bulkhead was also cracked so that water entered the forehold but was kept down to a few inches by the pumps. Bows swathed in tarpaulins.

**IIP Iceberg Number:** 

Position of Nearest Known Iceberg:

## **Ice Details**

Ice Briefing Received: Unknown

**Iceberg Population:** 

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Medium Length: 30 Width: Iceberg Tonnage: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

### **Route Details**

Geographic Area: Grand Banks	Origin: Swansea
Collision Latitude: 43 ° 55 ' " N	Destination: New York
Collision Longitude: 048 ° 23 ' " W	Distance:
Locale Accuracy: Known	Cargo at Event: General
Voyage:	
Displacement: Draft FWD (m):	
Captain's Experience: Unknown	
Radar Equipped?: Unknown	
Radar Details:	

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

