National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

# Ship-Iceberg Collision Incident Report



Page 1

## **Vessel Characteristics**

Name: Buzzard Flag: UK

ASPPR Ice Class: Unknown Lloyd's Class: Unknown

**Baltic Class:** Unknown

**Vessel Type:** Steamship Owner: Royal Navy

UK **Registered Country:** 

Year of Manufacture: 1887

Bow Shape: Unknown

Stem Angle:

Dimensions (m): Mass (tonnes):

Length: Gross: Beam: Net: Depth: Dead:

**Prime Mover:** Steam

Transmission: Unknown

Power (kW):

# Propellers:

Prop. Type: Unknown

Service Speed:

Stern Form:

Steel Grade: Unknown

#### **Miscellaneous Vessel Notes:**

British gunboat sloop believed to be the HMS

Sloop of Nymphe class. 1911 renamed "President". Now museun ship, London.

## **Collision Details**

Date: 23-Jun-1899

Visibility (nautical miles):

Visibility: Poor

Visibility - Snow:

Visibility - Fog: Fog

Night Visibility - Light:

**Collision Speed:** 10

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093 St. John's, Terre-Neuve

Unknown

St. John's, Newfoundland

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur: (709) 772-2462

Air Temperature: WaterTemperature:

Wind Speed:

WaveHeight:

Sea State: Unknown



## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Crushed Size - Length (m):

Location: Bow Size - Height (m):

Code: Plate Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Struck a growler or low lying iceberg at about 10 knots, 5 or 10 miles from Belle Isle, in fog at night while on fisheries protection trying to reach the French treaty shore.

#### **Damage Description:**

Stem stove, forcing it back and leaving a gaping hole in the bow. Required to be docked for repair and arrived St. John's June 25 or 26. Collison mats used to cover bows and guns and heavy gear moved top stern to raise bow.

### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

**Iceberg Size:** Growler Longitude: ° ' " W

Origin:

Destination:

Cargo at Event:

Distance:

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Strait of Belle Isle and

Collision Latitude: 50 ° 06 ' " N

Collision Longitude: 055 ° 33 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

