National Research
Council
Canada

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Conseil National de

Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

Name:CanadaPrime Mover:SteamFlag:Transmission:Unknown

ASPPR Ice Class: Unknown Power (kW):

Lloyd's Class: Unknown # Propellers:

 Baltic Class:
 Unknown

 Vessel Type:
 Passenger

 Service Speed:
 10

Owner: Cunard Line Stern Form:

Registered Country: UK Steel Grade: Unknown

Year of Manufacture: 1848 <u>Miscellaneous Vessel Notes:</u>

Bow Shape: Unknown Side paddle wheeler iron ship.

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

**Length:** 76.5 **Gross**: 1831

Beam: 11.6 Net: Depth: Dead:

### **Collision Details**

Date: 09-Jul-1859
Visibility (nautical miles):
Air Temperature:

Visibility: Poor WaterTemperature:

Visibility - Fog:Thick fogWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Daylight Sea State: Unknown

**Collision Speed:** 

Kerwin PlacePlace KerwinP.O. Box 12093C.P. 12093St. John's, NewfoundlandSt. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes Damage Report No.:

Scenario: Direct Impact Steel Failure Type:

Severity: Cracks Size - Length (m): Location: Bow Size - Height (m):

Code: Appendage Damage Below WL (m):

Damage Above WL - Height (m): Length of Downtime: Damage Above WL - Length (m): **Cost of Downtime:** 

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Hit a berg in dense fog on the Grand Banks.

## **Damage Description:**

Bowsprit, cutwater and headgear carried away. Left Halifax for Boston July 12. Taken into dry dock at Charlestown and damage found to be more serious and that her "apron" had been torn off at least 8' (2.4 m) below the main deck, and the ends of the planking on the starboard side so much affected as to require new ones.

## Ice Details

Ice Briefing Received: Unknown

**Iceberg Population: IIP Iceberg Number:** 

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093 St. John's, Terre-Neuve St. John's, Newfoundland A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Grand Banks

Collision Latitude:  $49 \, ^{\circ} \, 00 \, '$  " N

Collision Longitude: 048 ° 00 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: Liverpool

Destination: Halifax - Boston

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

