



National Research  
Council  
Canada

Conseil National de  
Recherches  
Canada

Institute for Ocean  
Technology

Institut des Technologies  
Océaniques

## Ship-Iceberg Collision Incident Report



Page 1 of 3

### Vessel Characteristics

<b>Name:</b> Dirigo	<b>Prime Mover:</b> Steam
<b>Flag:</b> USA	<b>Transmission:</b> Unknown
<b>ASPPR Ice Class:</b> Unknown	<b>Power (kW):</b>
<b>Lloyd's Class:</b> Unknown	<b># Propellers:</b>
<b>Baltic Class:</b> Unknown	<b>Prop. Type:</b> Unknown
<b>Vessel Type:</b> Passenger	<b>Service Speed:</b>
<b>Owner:</b> Alaska Steamship Co.	<b>Stern Form:</b>
<b>Registered Country:</b> USA	<b>Steel Grade:</b> Unknown
<b>Year of Manufacture:</b>	<b><u>Miscellaneous Vessel Notes:</u></b>
<b>Bow Shape:</b> Unknown	Passenger carrying steam schooner.
<b>Stem Angle:</b>	
<b><u>Dimensions (m):</u></b>	<b><u>Mass (tonnes):</u></b>
<b>Length:</b>	<b>Gross:</b>
<b>Beam:</b>	<b>Net:</b>
<b>Depth:</b>	<b>Dead:</b>

### Collision Details

<b>Date:</b> 28-Dec-1900	<b>Air Temperature:</b>
<b>Visibility (nautical miles):</b>	<b>Water Temperature:</b>
<b>Visibility:</b> Unknown	<b>Wind Speed:</b>
<b>Visibility - Fog:</b> Unknown	<b>Wave Height:</b>
<b>Visibility - Snow:</b> Unknown	<b>Sea State:</b> Unknown
<b>Visibility - Light:</b> Unknown	
<b>Collision Speed:</b>	
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



## Damage Details

---

**Damage Sustained:** Yes

**Damage Report No. :**

**Scenario:** Direct Impact

**Steel Failure Type:** Unknown

**Severity:** Crushed

**Size - Length (m):**

**Location:** Bow

**Size - Height (m):**

**Code:** Plate

**Damage Below WL (m):**

**Length of Downtime:**

**Damage Above WL - Height (m):**

**Cost of Downtime:**

**Damage Above WL - Length (m):**

**Cost to Repair:**

**No. Lives Lost:**

**No. Injuries:**

**Cause of Deaths/Injuries:** Unknown

**Cargo Loss:** Unknown

**Pollution:** Unknown

**Pollution Potential:** Unknown

**Cause of Damage:**

Hit a berg in Gastineau Channel, Alaska.

**Damage Description:**

Stem badly shattered below waterline, leaking.

## Ice Details

---

**Ice Briefing Received:** Unknown

**Iceberg Population:**

**IIP Iceberg Number:**

**Sea Ice Concentration:**

**Position of Nearest Known Iceberg:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown

Latitude: 0 ' " N

Iceberg Size: Unknown

Longitude: 0 ' " W

Length:

Date of Observation:

Width:

Iceberg Tonnage:

## Route Details

---

Geographic Area: Alaskan Waters

Origin:

Collision Latitude: 58 ° 20 ' " N

Destination: Juneau

Collision Longitude: 134 ° 27 ' " W

Distance:

Locale Accuracy: Known

Cargo at Event:

Voyage:

Displacement:

Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

