National Research
Council
Canada

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

Name:ElwoodPrime Mover:UnknownFlag:USATransmission:Unknown

ASPPR Ice Class: Power (kW):

Lloyd's Class: Unknown # Propellers:

Baltic Class: Unknown Prop. Type: Unknown

 Vessel Type:
 Fishing
 Service Speed:

 Owner:
 Captain Wyman
 Stern Form:

Registered Country: Steel Grade: Unknown
Year of Manufacture: Miscellaneous Vessel Notes:

Bow Shape: Unknown

Stem Angle:

Dimensions (m):Mass (tonnes):Length:Gross:Beam:Net:Depth:Dead:

Fishing schooner

### **Collision Details**

Date: 01-Feb-1895

Visibility (nautical miles):

Visibility: Unknown

WaterTemperature:

Visibility - Fog:UnknownWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Unknown Sea State: Unknown

Collision Speed:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's Newfoundland St. John's Terr

St. John's, Newfoundland St. John's, Terre-Neuve A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canada

## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: No Damage Report No. :

Scenario: Grounding on Steel Failure Type: Unknown

Severity: Unknown Size - Length (m):

Location: Bottom Size - Height (m):

Code: Unknown Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 0

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Left San Francisco January 24 in ballast but put in at Departure Bay for a cargo of coal for Juneau, Alaska. After discharging there headed for the Muir Glacier and passing through Icy Straits and when captain decided to moor to a large iceberg grounded on a reef neer Hoonah, Alaska and harvest ice.

### **Damage Description:**

30 tons stowed in hold when falling tide caused iceberg to tilt. As it did so a jagged under water spur raised the schooner out of the water resting in an ice cradle. Eventually slid along the ice and off into the water shipping several tons of water over the bows but without damage.

### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Origin:

Destination:

Cargo at Event:

Distance:

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Alaskan Waters

Collision Latitude: 58 ° 14 ' " N

Collision Longitude: 135 ° 27 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Kerwin Place

A1B 3T5

P.O. Box 12093

St. John's, Newfoundland

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

