National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report

1865

Mass (tonnes):

Gross:

Net:

Dead:



186.4

Page 1

Vessel Characteristics

Name: Erl King Flag: UK

Lloyd's Class:

Baltic Class:

ASPPR Ice Class: Unknown

Unknown Unknown

Vessel Type: Freighter

Owner: Robertson and Co. **Registered Country:** UK

Year of Manufacture:

Bow Shape: Unknown

Stem Angle:

Dimensions (m):

Length:

Beam:

Depth:

Prime Mover: Steam

Transmission:

Unknown

Unknown

Power (kW):

Propellers:

Prop. Type:

Service Speed:

Stern Form:

2193

Steel Grade: Unknown

Miscellaneous Vessel Notes:

Iron steamer, chartered by Donaldson Line and captained by captain Briske of Glasgow. 1891 wrecked. The Evening Telegram lists the owner as 'Ross of Glasgow'.

Collision Details

Date: 05-Aug-1885

Visibility: Unknown

Visibility (nautical miles):

Visibility - Fog: Thick fog Visibility - Snow: Unknown

Visibility - Light: Unknown Air Temperature:

WaterTemperature:

Wind Speed: WaveHeight:

Sea State: Unknown

Collision Speed:

Kerwin Place P.O. Box 12093

St. John's, Newfoundland A1B 3T5

Fax:(709) 772-2462

Place Kerwin C.P. 12093

St. John's, Terre-Neuve

A1B 3T5

Télécopieur: (709) 772-2462



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No.:

Scenario: Glancing Blow Steel Failure Type:

Severity: Hole Size - Length (m): Location: Bow Size - Height (m):

Code: Plate Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m): Damage Above WL - Length (m): **Cost of Downtime:**

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Hit a berg in the North Atlantic, 150 miles from St. John's.

Damage Description:

Hole in starboard bow above waterline; bow and bulwarks damaged. Put into St. John's August 14 and repaired by ship's carpenter, Daniel Condon.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093 St. John's, Terre-Neuve St. John's, Newfoundland

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: $45\ ^{\circ}\ 50\ '$ " N

Collision Longitude: 050 ° 10 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Montreal

Destination: London

Distance:

Cargo at Event: Livestock

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

