National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

# Ship-Iceberg Collision Incident Report

1

Page 1

## **Vessel Characteristics**

Name: Ethiopia

UK

**ASPPR Ice Class:** Unknown

Lloyd's Class:

Flag:

Unknown

**Baltic Class:** 

Unknown

**Vessel Type:** 

Passenger / Cargo

UK

122.5

1873

Mass (tonnes):

Gross:

Net:

Dead:

Owner: Anchor Line

**Registered Country:** 

Year of Manufacture:

Bow Shape: Unknown

Stem Angle:

Dimensions (m):

Length:

Beam: 12.25

Depth:

Prime Mover: Steam

Transmission:

Unknown

Unknown

13

Power (kW):

# Propellers:

Prop. Type:

Service Speed:

Stern Form:

Steel Grade:

Unknown

**Miscellaneous Vessel Notes:** 

1907 scrapped.

## **Collision Details**

Date: 06-Jun-1894

Visibility (nautical miles):

Visibility: Poor

Visibility - Fog: Fog

Visibility - Snow: Unknown

Daylight Visibility - Light:

**Collision Speed:** 12

Kerwin Place P.O. Box 12093

St. John's, Newfoundland

A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve

A1B 3T5 Télécopieur: (709) 772-2462 Air Temperature:

4005

WaterTemperature:

Wind Speed:

WaveHeight:

Sea State: Unknown



## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Crushed Size - Length (m): 5

Location: Bow Size - Height (m):

Code: Hole Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

From New York, June 2, hit a berg with great force in the North Atlantic in the afternoon of June 6 during a heavy fog 200 miles SW of the Flemish Cap. At 2:30 pm travelling at 12 knots in visibility of no further than yards, enogines suddenly stopped and after a lull of 5 seconds came a tremendous crash. "A vast white mountain of ice" seen moments after.

#### **Damage Description:**

Orders given to abandon ship but found that the pumps were handling the leak through a hole in the bows. Bow above waterline badly stove and broken, bulkheads tight, forward compartment full of water. Canvas used to strengthen bulkhead and kegs of flour used to damn hole. Littlle flour spoiled. Cargo in the forehold moved to stern to raise bows and most voyage completed at quarter speed. Nobody injured despite having been thrown to the floor at impact. Arrived Glasgow June 16.

### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Large Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Grand Banks

Collision Latitude: 45  $^{\circ}$  06  $^{\prime}$  " N

Collision Longitude: 045 ° 03 ' " W

Locale Accuracy: Unknown

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: New York

**Destination:** Glasgow

Distance:

Cargo at Event: Flour

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

