National Research Council

Council

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: George W. Elder

Steam

Flag: USA

ASPPR Ice Class: Unknown

Transmission: Power (kW):

Prime Mover:

Unknown

Lloyd's Class:

Unknown

Propellers:

1

Baltic Class:

Unknown

Prop. Type:

Unknown

Vessel Type:

Passenger / Cargo

Service Speed:

10

Owner: Pacific Coast Steamship Co.

Stern Form:

Registered Country:

USA

Steel Grade: Unknown

Bow Shape: Unknown

Year of Manufacture: 1874

Miscellaneous Vessel Notes:

. . .

Stem Angle:

Dimensions (m):

Mass (tonnes):

Gross:

1710

Length: Beam: Depth: 76.2 11.6 6.4

Net: Dead: 1225 1400

Collision Details

Date: 01-Sep-1890

Visibility (nautical miles):

Air Temperature:

Visibility: Unknown

WaterTemperature:

Visibility - Fog:

Unknown

Wind Speed:

Visibility - Snow:

Unknown

WaveHeight:

Visibility - Light:

Unknown

Sea State: Unknown

Collision Speed:

5

Kerwin Place P.O. Box 12093

Fax:(709) 772-2462

A1B 3T5

Place Kerwin C.P. 12093

St. John's, Newfoundland

St. John's, Terre-Neuve

A1B 3T5

Télécopieur:(709) 772-2462

Terre-Neuve Canada

Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Hole Size - Length (m): 1

Location: Bow Size - Height (m): 1

Code: Plate Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Hit a berg, mostly submerged, at half speed in Glacier Bay, Alaska.

Damage Description:

Jagged hole in port bow, 3' by 3' (1 by 1 m) and in 20 minutes 12 feet of water were found in the hold. Imediately beached to avoid sinking and patched. Arrived Victoria September 9.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Growler Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Alaskan Waters

Collision Latitude: 58 ° 30 ' " N

Collision Longitude: 135 $^{\circ}$ 00 $^{\prime}$ " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Alaska

Destination: Victoria

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

