



National Research  
Council  
Canada

Conseil National de  
Recherches  
Canada

Institute for Ocean  
Technology

Institut des Technologies  
Océaniques

## Ship-Iceberg Collision Incident Report



Page 1 of 3

### Vessel Characteristics

<b>Name:</b> Hegira	<b>Prime Mover:</b> Steam
<b>Flag:</b> USA?	<b>Transmission:</b> Unknown
<b>ASPPR Ice Class:</b> Unknown	<b>Power (kW):</b>
<b>Lloyd's Class:</b> Unknown	<b># Propellers:</b>
<b>Baltic Class:</b> Unknown	<b>Prop. Type:</b> Unknown
<b>Vessel Type:</b> Steamship	<b>Service Speed:</b>
<b>Owner:</b> U.S. Shipping Board	<b>Stern Form:</b>
<b>Registered Country:</b> USA	<b>Steel Grade:</b> Unknown
<b>Year of Manufacture:</b> 1919	<b><u>Miscellaneous Vessel Notes:</u></b>
<b>Bow Shape:</b> Unknown	Listed by ABS as a screw.
<b>Stem Angle:</b>	
<b><u>Dimensions (m):</u></b>	<b><u>Mass (tonnes):</u></b>
<b>Length:</b> 134.1	<b>Gross:</b> 7890
<b>Beam:</b> 17.1	<b>Net:</b> 5054
<b>Depth:</b> 10.7	<b>Dead:</b>

### Collision Details

<b>Date:</b> 25-Aug-1922	<b>Air Temperature:</b>
<b>Visibility (nautical miles):</b>	<b>Water Temperature:</b>
<b>Visibility:</b> Unknown	<b>Wind Speed:</b>
<b>Visibility - Fog:</b> Unknown	<b>Wave Height:</b>
<b>Visibility - Snow:</b> Unknown	<b>Sea State:</b> Unknown
<b>Visibility - Light:</b> Unknown	
<b>Collision Speed:</b>	
Kerwin Place	Place Kerwin
P.O. Box 12093	C.P. 12093
St. John's, Newfoundland	St. John's, Terre-Neuve
A1B 3T5	A1B 3T5
Fax:(709) 772-2462	Télécopieur:(709) 772-2462



## Damage Details

---

**Damage Sustained:** Unknown

**Damage Report No. :**

**Scenario:** Glancing Blow

**Steel Failure Type:** Unknown

**Severity:** Unknown

**Size - Length (m):**

**Location:** Unknown

**Size - Height (m):**

**Code:** Unknown

**Damage Below WL (m):**

**Length of Downtime:**

**Damage Above WL - Height (m):**

**Cost of Downtime:**

**Damage Above WL - Length (m):**

**Cost to Repair:**

**No. Lives Lost:**

**No. Injuries:**

**Cause of Deaths/Injuries:** Unknown

**Cargo Loss:** Unknown

**Pollution:** Unknown

**Pollution Potential:** Unknown

**Cause of Damage:**

Grazed by 2 large icebergs when she sailed between them.

**Damage Description:**

Presumed not serious.

## Ice Details

---

**Ice Briefing Received:** Unknown

**Iceberg Population:**

**IIP Iceberg Number:**

**Sea Ice Concentration:**

**Position of Nearest Known Iceberg:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

# Ship-Iceberg Collision Incident Report



Page 3 of 3

**Iceberg Shape:** Unknown

**Latitude:** 0 ° ' " N

**Iceberg Size:** Unknown

**Longitude:** 0 ° ' " W

**Length:**

**Date of Observation:**

**Width:**

**Iceberg Tonnage:**

## Route Details

---

**Geographic Area:** Grand Banks

**Origin:** Galveston

**Collision Latitude:** 42 ° 30 ' " N

**Destination:** Havre

**Collision Longitude:** 050 ° 00 ' " W

**Distance:**

**Locale Accuracy:** Known

**Cargo at Event:**

**Voyage:**

**Displacement:**

**Draft FWD (m):**

**Captain's Experience:** Unknown

**Radar Equipped?:** Unknown

**Radar Details:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

