National Research Council

Council Canada Conseil National de

Recherches Canada

Institute for Ocean

Institut des Technologies

Technology Océaniques

# Ship-Iceberg Collision Incident Report

NAC-CNAC

6

Page 1 of 3

## **Vessel Characteristics**

Name: Hugo

Flag:

ASPPR Ice Class: Unknown

Lloyd's Class: Unknown

Baltic Class: Unknown

Vessel Type: Steamship

Owner: Irrawaddy Flotilla Company Ltd.

Registered Country: United Kingdom

Year of Manufacture:

Bow Shape: Unknown

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

 Length:
 30.7
 Gross:
 92

 Beam:
 6.9
 Net:
 46

1903

Depth: 1.9 Dead:

Prime Mover: Steam

Transmission: Unknown

Power (kW):

# Propellers:

Prop. Type: Unknown

Service Speed:

Stern Form:

Steel Grade: Unknown

**Miscellaneous Vessel Notes:** 

Steel steamer.

### **Collision Details**

Date: 01-May-1927

Visibility (nautical miles):

Visibility: Unknown

Unknown

Visibility - Snow: Unknown

Unknown

Air Temperature:

WaterTemperature:

Wind Speed:

WaveHeight:

Sea State: Unknown

Visibility - Light: Collision Speed:

Visibility - Fog:

Kerwin Place P.O. Box 12093

P.O. Box 12093 St. John's, Newfoundland

St. John's, Newfoundland A1B 3T5

Fax:(709) 772-2462

Place Kerwin C.P. 12093

St. John's, Terre-Neuve

A1B 3T5

Télécopieur:(709) 772-2462

Canadä

## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes	Damage Report No. :
-----------------------	---------------------

Scenario: Unknown Steel Failure Type: Unknown

Severity: Sinking Size - Length (m):

Location: Unknown Size - Height (m):

Code: Unknown Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Fall to Deck

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Steamer disappeared with all hands and thought to have hit a berg off Cape Farewell on voyage from Denmark to Greenland. Lat - Ion estimated.

#### **Damage Description:**

Sunk

## Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Labrador Sea and Davi

Collision Latitude:  $59 \, ^{\circ} \, 30 \, ' \, N$ 

Collision Longitude: 052 ° ' " W

Locale Accuracy: Unknown

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: Ivigtut, Greenland

**Destination:** Copenhagen

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

