

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

Name: Innerton Prime Mover: Steam	
Flag: UK Transmission: Unknown	
ASPPR Ice Class: Unknown Power (kW):	
Lloyd's Class: Unknown # Propellers:	1
Baltic Class:   Unknown   Prop. Type:   Unknown	
Vessel Type:FreighterService Speed:11	
Owner: Carlton Steamship Co. (R.Chapman & Son), New Stern Form:	
Registered Country: UK Steel Grade: Unknown	
Year of Manufacture: 1919 <u>Miscellaneous Vessel Notes:</u>	
Bow Shape: Unknown Laid down as "War Scilla", laid	unched as
Stem Angle: Innerton.   Sunk as blockship at Normar 1944, thereafter salved and s	
Dimensions (m): Mass (tonnes):	
Length: 125.6 Gross: 5276	
Beam: 15.9 Net:	
Depth: 8.7 Dead: 3421	

## **Collision Details**

Date: 02-Jun-1926			
Visibility (nautical miles):		Air Temperature:	
Visibility: Poor		WaterTemperature:	
Visibility - Fog: Fog		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Night		Sea State: Unknown	
<b>Collision Speed:</b> Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

Ship-Iceberg Collision Incident Report



### **Damage Details**

Damage Sustained: Yes	Damage Report No. :	
Scenario: Direct Impact	Steel Failure Type: Unknown	
Severity: Crushed	Size - Length (m):	
Location: Bow	Size - Height (m):	
Code: Plate	Damage Below WL (m):	
Length of Downtime:	Damage Above WL - Height (m):	
Cost of Downtime:	Damage Above WL - Length (m):	
Cost to Repair:		
No. Lives Lost:		
No. Injuries:	Cause of Deaths/Injuries: Unknown	
Cargo Loss: Unknown		
Pollution: Unknown	Pollution Potential: Unknown	

#### Cause of Damage:

Hit a berg 240 miles (386 km) SE of St. John's head on. 20 spotted, some large. IIP has a position for this vessel and a small iceberg on June 1 at 42°08'N 49°15 which could be the one given a day error.

#### **Damage Description:**

Arrived St. John's June 2 with bows badly damaged; 42 plates. Bow from keel to hawser pipes stove in. Forepeak full of water. Unable to drop anchors because of damage.

**IIP Iceberg Number:** 

Position of Nearest Known Iceberg:

### **Ice Details**

Ice Briefing Received: Unknown

Iceberg Population: 20

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



of 3

Iceberg Shape: Unknown Iceberg Size: Small Length: Width: Latitude: ° ' " N

Page 3

Longitude: ° ' " W

Date of Observation:

### **Route Details**

Iceberg Tonnage:

Geographic Area: Grand Banks	Origin: Port Said, Egypt			
Collision Latitude: 42 ° 08 ' " N	Destination: Montreal			
Collision Longitude: 049 ° 15 ' " W	Distance:			
Locale Accuracy: Known Vovage:	Cargo at Event:			
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

