National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean

Institut des Technologies

Technology Océaniques

Ship-Iceberg Collision Incident Report



Page 1

Vessel Characteristics

Name: John Rutledge

Flag: USA

ASPPR Ice Class: Unknown

Lloyd's Class:

Unknown

Baltic Class:

Unknown

Vessel Type:

Sailing Vessel

Owner: New York and Liverpool Packet Co.

Registered Country:

USA

Year of Manufacture:

Unknown

Bow Shape:

Stem Angle:

Dimensions (m):

Length:

Beam:

Depth:

Mass (tonnes): Gross:

1852

Net:

1060

Dead:

Prime Mover: Sail

Transmission: Unknown

Unknown

Power (kW):

Propellers:

Prop. Type:

Service Speed:

Stern Form:

Steel Grade: Unknown

Miscellaneous Vessel Notes:

Owned by Messrs. Howland and Ridgeway and engaged as a regular packet between New York and Liverpool. Built in Baltimore. NYH quotes 1852, other sources c.1840.

Collision Details

Date: 20-Feb-1856

Visibility (nautical miles):

Visibility: Unknown

Visibility - Fog: Mist

Visibility - Snow:

Daylight Visibility - Light:

Unknown

Air Temperature:

WaterTemperature:

Wind Speed: 10

WaveHeight:

Sea State: Unknown

Collision Speed:

Kerwin Place P.O. Box 12093

St. John's, Newfoundland

A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093

St. John's, Terre-Neuve A1B 3T5

Télécopieur: (709) 772-2462

Canada

Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Sinking Size - Length (m):

Location: Bow Size - Height (m):

Code: Hole Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 135

No. Injuries: Cause of Deaths/Injuries: Hypothermia/frostbite

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Struck a berg on the Grand Banks shortly before 10 a.m. Steady breeze. Came into contact with an iceberg under the bow starboard side. This could mean a growler or field ice. A couple of different locations have been given, one at about 45°30'N 45°56'W and the other at 46°N and 52°W. Passed first icebergs on 18th in 46°34'N, 46°56'W. In and out of ice oveer the next day with light winds and sail make latter position

Damage Description:

Bow holed and cargo shifted and jettisoned, quilts and mattresses put in place but nothing would contain the leak and the vessel was abandoned a few hours later. All but 2 of the approximately 136 passengers and crew took to 5 boats. All but one of those perished over the next 9 days before being rescued by the "Germania".

John Rutledge at:

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Growler Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: 45 $^{\circ}$ 30 $^{\prime}$ " N

Collision Longitude: 045 $^{\circ}$ 56 $^{\prime}$ " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Liverpool

Destination: New York

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

