National Research Council

Council

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

# Ship-Iceberg Collision Incident Report



1

Page 1 of 3

## **Vessel Characteristics**

Name: Lake Anja
Flag: Norway

ASPPR Ice Class: Unknown
Lloyd's Class: Unknown

Baltic Class: Unknown

Vessel Type: Tanker

Owner: Bakri Navigation Co. Ltd.

Registered Country: Norway

Year of Manufacture: 1963

Bow Shape: Unknown

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

 Length:
 169.75
 Gross:
 13044

 Beam:
 21.95
 Net:
 7494

 Depth:
 9.399
 Dead:
 20780

Transmission: Unknown

**Power (kW):** 6710

Oil Engine

# Propellers:

**Prop. Type:** Fixed Pitch (FP)

Service Speed: 15

Stern Form:

Prime Mover:

Steel Grade: Unknown

Miscellaneous Vessel Notes:

Buil as "Gard". Renamed "Gimlekollen" 1975. Renamed "Lake Anja" 1977.

Renamed "Mohammed Al-Bakry " 1984. Renamed "Mohammed Al-Bakry X" 1984.

Dead 1990.

### **Collision Details**

**Date:** 07-May-1980

Visibility (nautical miles):

Air Temperature: 2

Visibility: Unknown

WaterTemperature:

Visibility - Fog:FogWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Unknown Sea State: Ice covered - Moderate

**Collision Speed:** 

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canadä

## Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Unknown Steel Failure Type: Unknown

Severity: Unknown Size - Length (m):

Location: Bow Size - Height (m):

Code: Unknown Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 0

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Growler in pack ice. No IIP iceberg reports from area.

**Damage Description:** 

Damage to bow and port wing tank. Vessel was repaired in Newfoundland.

### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



of 3 Page 3

" N Iceberg Shape: Latitude: Unknown

Iceberg Size: Growler Longitude: " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

## **Route Details**

Geographic Area: Strait of Belle Isle and

51 ° 36 ' **Collision Latitude:** 

Collision Longitude: 056 ° 15 '

Locale Accuracy: Known

Voyage:

Displacement:

Draft FWD (m): 9.7

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

St. John's, Newfoundland

A1B 3T5 Fax:(709) 772-2462

Kerwin Place

P.O. Box 12093

Cargo at Event:

Origin:

Destination:

Distance:

Canada