

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Manchester Commerce		Pri	ime Mover: Steam		
Flag: UK			Tra	ansmission: Unknown	
ASPPR Ice Class:	Unknown		Ро	ower (kW):	
Lloyd's Class:	Unknown		# F	Propellers:	
Baltic Class:	Unknown		Pro	op. Type: Unknown	
Vessel Type:	ssel Type: Steamship		Se	Service Speed:	
Owner: Manchester Liners Ltd.			Ste	ern Form:	
Registered Country: UK			Ste	eel Grade: Unknown	
Year of Manufacture: 1899			Miscellaneous Vessel Notes:		
Bow Shape: Unknown				Mined and sunk off Ireland 1914. Manchester	
Stem Angle:				line a subsidiary of Furness, Withy & Co.	
Dimensions (m):	Mass	(tonnes):			
Length:		Gross:	5363		
Beam: Depth:		Net: Dead:	3444		
Deptil.		Deau.			

Collision Details

Date: 01-Nov-1913			
Visibility (nautical miles): 25		Air Temperature:	
Visibility: Good		WaterTemperature:	
Visibility - Fog: Clear		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Low light		Sea State: Unknown	
Collision Speed:	12		
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :			
Scenario: Direct Impact	Steel Failure Type: Unknown			
Severity: Crushed	Size - Length (m):			
Location: Bow	Size - Height (m):			
Code: Plate	Damage Below WL (m):			
Length of Downtime: 2 months	Damage Above WL - Height (m):			
Cost of Downtime:	Damage Above WL - Length (m):			
Cost to Repair:				
No. Lives Lost: No. Injuries:	Cause of Deaths/Injuries: Unknown			
Cargo Loss: Unknown Pollution: Unknown	Pollution Potential: No			

Cause of Damage:

Struck a large low lying berg at full speed [12 kts?] 100 miles E of the Strait of Belle Isle early in the morning at 3 a.m. Weather clear and fine and lights could be seen for 25 miles (40 km).

Damage Description:

Severe damage, bows crushed to forward bulkhead. Plates on port side bent over starboard. Leaking port side. Hole in starboard bow above waterline. Arrived St. John's November 4, repairs estimated at 2 months.

IIP Iceberg Number:

Position of Nearest Known Iceberg:

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Iceberg Shape: Tabular Iceberg Size: Large Length: Width: Iceberg Tonnage: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

Route Details

Geographic Area: Strait of Belle Isle and	Origin: Montreal				
Collision Latitude: 51 ° 40 ' " N	Destination: Manchester				
Collision Longitude: 052 ° 38 ' "W	Distance:				
Locale Accuracy: Known	Cargo at Event: General cargo, apples, cheese, deals and pulp.				
Voyage:					
Displacement:					
Draft FWD (m):					
Captain's Experience: Unknown					
Radar Equipped?: Unknown					
Radar Details:					

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

