National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

# Ship-Iceberg Collision Incident Report

240.1

Page 1

Steam

Unknown

#### **Vessel Characteristics**

Name: Mancunia Flag: USA

ASPPR Ice Class: Unknown

Lloyd's Class: **Baltic Class:** Unknown

**Vessel Type:** 

Steamship

Owner: Seatonia Steamship Company Ltd.

**Registered Country:** Year of Manufacture:

United Kingdom

1898

Mass (tonnes):

Gross:

Dead:

Net:

Bow Shape:

Unknown

Stem Angle:

Dimensions (m):

Length: Beam: Depth:

105.2 15.6

7.4

Prime Mover:

Transmission:

Unknown

Power (kW):

# Propellers:

Prop. Type:

Service Speed:

Stern Form:

Air Temperature:

Wind Speed:

WaveHeight:

WaterTemperature:

Sea State: Unknown

3533

2287

3286

Steel Grade: Unknown

**Miscellaneous Vessel Notes:** 

An American vessel of this name built 1898.

#### **Collision Details**

Date: 30-May-1915

Visibility (nautical miles):

Visibility: Unknown

Unknown

Visibility - Snow:

Visibility - Fog:

Visibility - Light:

Unknown

Unknown

**Collision Speed:** Kerwin Place

P.O. Box 12093 St. John's, Newfoundland

A1B 3T5

Fax:(709) 772-2462

Place Kerwin C.P. 12093

St. John's, Terre-Neuve A1B 3T5

Télécopieur:(709) 772-2462

Canada

## Ship-Iceberg Collision Incident Report



Page 2 of 3

### **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Hole Size - Length (m):

Location: Bow Size - Height (m):

Code: Plate Damage Below WL (m):

Length of Downtime: 19 Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Struck a growler N of St. John's and docked at Chance Harbour to survey damages. Lat - Lon estimated.

#### **Damage Description:**

Serious damage, leaking badly, and returned to St. John's for dry dock and repairs departing again June 19 with several new plates put on bow.

#### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Growler Longitude: 0 " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

**Route Details** 

Geographic Area: Grand Banks

Collision Latitude: 49  $^{\circ}$  38  $^{\prime}$  " N

Collision Longitude: 054 ° 49 ' " W

Locale Accuracy: Estimated

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: Cardiff

**Destination:** Lewisporte

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

