

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

| Name:                          | Montcalm                |           |        | Pr    | me Mover:                | Steam                          |
|--------------------------------|-------------------------|-----------|--------|-------|--------------------------|--------------------------------|
| Flag:                          | Canada                  |           |        | Tra   | ansmission:              | Unknown                        |
| ASPPR Ice Class: Unknown       |                         |           |        |       | wer (kW):                |                                |
| Lloyd's                        | Class:                  | Unknown   |        | # F   | Propellers:              | 2                              |
| Baltic C                       | lass:                   | Unknown   |        | Pr    | ор. Туре:                | Unknown                        |
| Vessel <sup>-</sup>            | Туре:                   | Passenger |        | Se    | rvice Speed              | 16                             |
| Owner:                         | Owner: Canadian Pacific |           |        |       |                          |                                |
| Registered Country: UK         |                         |           |        | St    | eel Grade:               | Unknown                        |
| Year of Manufacture: 1920      |                         |           |        | Mi    | scellaneous              | Vessel Notes:                  |
| Bow Shape: Unknown             |                         |           |        |       | ohn Brown & Co, Glasgow. |                                |
| Stem A                         | ngle:                   |           |        |       | Renamed                  | HMS Wolfe 1939, Scrapped 1952. |
| Dimensions (m): Mass (tonnes): |                         |           |        |       |                          |                                |
| Leng                           | gth:                    | 167.9     | Gross: | 16418 |                          |                                |
| Bear                           |                         | 21.4      | Net:   | 0     |                          |                                |
| Dept                           | :h:                     |           | Dead:  |       |                          |                                |
|                                |                         |           |        |       |                          |                                |

## **Collision Details**

| Date: 03-Jul-1927  |  |                    |        |
|--|--|--------------------|--------|
| Visibility (nautical miles):   |  | Air Temperature:   |        |
| Visibility: Poor   |  | WaterTemperature:  |        |
| Visibility - Fog: Fog  |  | Wind Speed:        |        |
| Visibility - Snow: Unknown   |  | WaveHeight:        |        |
| Visibility - Light: Daylight   |  | Sea State: Unknown |        |
| <b>Collision Speed:</b><br>Kerwin Place<br>P.O. Box 12093<br>St. John's, Newfoundland<br>A1B 3T5<br>Fax:(709) 772-2462 | Place Kerwin<br>C.P. 12093<br>St. John's, Terre-Neuve<br>A1B 3T5<br>Télécopieur:(709) 772-2462 |                    | Canadä |

## Ship-Iceberg Collision Incident Report



## **Damage Details**

| Damage Sustained: Yes         | Damage Report No. :               |  |  |  |  |
|-------------------------------|-----------------------------------|--|--|--|--|
| Scenario: Striking projection | Steel Failure Type: Unknown       |  |  |  |  |
| Severity: Denting             | Size - Length (m):                |  |  |  |  |
| Location: Propeller           | Size - Height (m):                |  |  |  |  |
| Code: Propulsor               | Damage Below WL (m):              |  |  |  |  |
| Length of Downtime:           | Damage Above WL - Height (m):     |  |  |  |  |
| Cost of Downtime:             | Damage Above WL - Length (m):     |  |  |  |  |
| Cost to Repair:               |                                   |  |  |  |  |
| No. Lives Lost:               |                                   |  |  |  |  |
| No. Injuries:                 | Cause of Deaths/Injuries: Unknown |  |  |  |  |
| Cargo Loss: Unknown           |                                   |  |  |  |  |
| Pollution: Unknown            | Pollution Potential: Unknown      |  |  |  |  |

#### Cause of Damage:

Struck along a submerged projection of an iceberg on Sunday afternoon in dense fogs in the Strait of Belle Isle. Passengers heard a crunching noise and vessel heaved over and slid along before righting herself. Top of iceberg was high over height of funnels.

#### **Damage Description:**

Though lifeboats were swung out, apparantly no seriuos damage with scrapes along the bilge keel and one propeller blade bent. Arrived London 10 July.

**IIP Iceberg Number:** 

Position of Nearest Known Iceberg:

## **Ice Details**

Ice Briefing Received: Unknown

**Iceberg Population:** 

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



of 3

Iceberg Shape: Unknown Iceberg Size: Large Length: Width:

Page 3 " N Latitude: 0 ,

• ' " W Longitude:

Date of Observation:

## **Route Details**

Iceberg Tonnage:

| Geographic Area: Strait of Belle Isle and | Origin: Montreal    |  |  |  |  |
|---|---------------------|--|--|--|--|
| Collision Latitude: 51 ° ' " N            | Destination: Canada |  |  |  |  |
| Collision Longitude: 054 ° 07 ' " W       | Distance:           |  |  |  |  |
| Locale Accuracy: Known                    | Cargo at Event:     |  |  |  |  |
| Voyage:                                   |                     |  |  |  |  |
| Displacement:<br>Draft FWD (m):           |                     |  |  |  |  |
| Captain's Experience: Unknown             |                     |  |  |  |  |
| Radar Equipped?: Unknown                  |                     |  |  |  |  |
| Radar Details:                            |                     |  |  |  |  |

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

