National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report



Page 1

Unknown

Unknown

Vessel Characteristics

Greece

Flag:

Name: Omikronventure L.

ASPPR Ice Class: Unknown Lloyd's Class: Unknown

Baltic Class: Unknown Prop. Type: Unknown

Ore / Bulk / Oil Carrier, Tanker **Vessel Type:** Service Speed: Owner: Bella Maritime Corp. / Ceres Hellenic Shipping Stern Form:

Steel Grade: **Registered Country:** Poland Unknown

Year of Manufacture: 1987 **Miscellaneous Vessel Notes:**

Bow Shape: Unknown

Dimensions (m): Mass (tonnes):

Length: 250 Gross: 59850 Beam: 41.6 Net: 31108 Depth: 20 Dead: 97179

Prime Mover:

Transmission:

Power (kW):

Propellers:

Built as "Berge Gdansk". Renamed "Arrow Gdansk" 1987. Renamed "Omikronventure L." 1988. Renamed "Glenbuck" 2000.

Collision Details

Stem Angle:

Date: 28-Apr-1993

Air Temperature: Visibility (nautical miles):

WaterTemperature: Visibility: Good

Wind Speed: Visibility - Fog: Unknown WaveHeight: Visibility - Snow: Unknown

Sea State: Moderate Visibility - Light: Low light

Collision Speed:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Terre-Neuve St. John's, Newfoundland

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur: (709) 772-2462



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Unknown Steel Failure Type: Unknown

Severity: Cracks Size - Length (m): 7

Location: Bow and tanks Size - Height (m): 3

Code: Plate Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 0

No. Injuries: 0 Cause of Deaths/Injuries: Unknown

Cargo Loss: No

Pollution: No Pollution Potential: Yes

Cause of Damage:

Struck a growler in an area of sea ice and icebergs in evening twilight at 2125Z. Had good ice warnings.

Damage Description:

Vessel sustained crack in her forepeak tank and No. 1 starboard ballast tank, flooding both. Cargo tanks intact. Crack temporarily patched and made watertight by crew and vessel continued voyage to New York down by the head. Damage was later found to be a 1" (2.5 cm) horizontal crack 3' (0.9 m) long below the waterline just aft of the forecastle. A 7 by 3 meter hole was also found on the port side of the forepeak tank just below the waterline.

Ice Details

Ice Briefing Received: Ice Reports Receive

Iceberg Population: 10 IIP Iceberg Number: 2256

Sea Ice Concentration: 5 Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Newfoundland St. John's, Terre-Neuve A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canadä

Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: 47 ° 47 ′ 06 " N

Iceberg Size: Growler Longitude: 048 ° 01 ' 41 " W

Length: Date of Observation: 28-Apr-1993

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: 47 ° 50 ' " N

Collision Longitude: 048 ° 21 ' " W

Locale Accuracy: Known

Voyage:

Displacement:

Draft FWD (m): 14.52

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Mongstad, Norway

Destination: New York

Distance:

Cargo at Event: 600000 barrels of crude oil

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

