



National Research
Council
Canada

Conseil National de
Recherches
Canada

Institute for Ocean
Technology

Institut des Technologies
Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Player	Prime Mover: Sail
Flag:	Transmission: Unknown
ASPPR Ice Class: Unknown	Power (kW):
Lloyd's Class: 1A	# Propellers:
Baltic Class: Unknown	Prop. Type: Unknown
Vessel Type: Sailing Vessel	Service Speed:
Owner:	Stern Form:
Registered Country:	Steel Grade: Unknown
Year of Manufacture:	

Miscellaneous Vessel Notes:

Likely a fishing schooner built in Newfoundland. Issac Young, Captain.

Bow Shape: Unknown
Stem Angle:

Dimensions (m):

Length:
Beam:
Depth:

Mass (tonnes):

Gross:
Net:
Dead:

0

Collision Details

Date: 01-Jul-1915

Visibility (nautical miles):

Visibility: Unknown

Visibility - Fog: Unknown

Visibility - Snow: Unknown

Visibility - Light: Unknown

Collision Speed:

Kerwin Place
P.O. Box 12093
St. John's, Newfoundland
A1B 3T5
Fax:(709) 772-2462

Place Kerwin
C.P. 12093
St. John's, Terre-Neuve
A1B 3T5
Télécopieur:(709) 772-2462

Air Temperature:

WaterTemperature:

Wind Speed:

WaveHeight:

Sea State: Unknown



Damage Details

Damage Sustained: Yes	Damage Report No. :
Scenario: Direct Impact	Steel Failure Type: Unknown
Severity: Hole	Size - Length (m):
Location: Bow	Size - Height (m):
Code: Plate	Damage Below WL (m):
Length of Downtime:	Damage Above WL - Height (m):
Cost of Downtime:	Damage Above WL - Length (m):
Cost to Repair:	
No. Lives Lost:	
No. Injuries:	Cause of Deaths/Injuries: Unknown
Cargo Loss: Unknown	
Pollution: Unknown	Pollution Potential: Unknown

Cause of Damage:

Struck a growler on way to St. John's from Twillingate with herring. Lat and lon estimated.

Damage Description:

Vessel headgear much damaged and the pumps had to be kept going constantly.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

IIP Iceberg Number:

Sea Ice Concentration:

Position of Nearest Known Iceberg:

Kerwin Place
P.O. Box 12093
St. John's, Newfoundland
A1B 3T5
Fax:(709) 772-2462

Place Kerwin
C.P. 12093
St. John's, Terre-Neuve
A1B 3T5
Télécopieur:(709) 772-2462

Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown

Latitude: 0 ' " N

Iceberg Size: Growler

Longitude: 0 ' " W

Length:

Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Strait of Belle Isle and

Origin: Twillingate

Collision Latitude: 49 ° 30 ' " N

Destination: St. John's

Collision Longitude: 053 ° 30 ' " W

Distance:

Locale Accuracy: Estimated

Cargo at Event: Herring

Voyage:

Displacement:

Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place
P.O. Box 12093
St. John's, Newfoundland
A1B 3T5
Fax:(709) 772-2462

Place Kerwin
C.P. 12093
St. John's, Terre-Neuve
A1B 3T5
Télécopieur:(709) 772-2462

