National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean

Institut des Technologies

Technology Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

### **Vessel Characteristics**

Name:QueensgarthPrime Mover:Oil EngineFlag:UKTransmission:Unknown

 ASPPR Ice Class:
 Unknown
 Power (kW):
 3311

 Lloyd's Class:
 100A1
 # Propellers:
 1

Baltic Class: Unknown Prop. Type: Fixed Pitch (FP)

Vessel Type: Ore Carrier Service Speed: 12

Owner: St. Denis Shipping Co. Ltd. Stern Form:

Registered Country: UK Steel Grade: Unknown

Year of Manufacture: 1959 <u>Miscellaneous Vessel Notes:</u>

Bow Shape: Unknown Single screw ore carrier

•

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

 Length:
 155.7
 Gross:
 10762

 Beam:
 21.4
 Net:
 5470

**Depth:** 11.05 **Dead:** 15000

Single screw ore carrier, converted to drill

ship later on.

Renamed "Dapo Star" 1977. Renmamed "Australind" 1981. Renamed "Eniwetok" 1981. Renamed "Five Star" 1985. Renamed "Stardrill" 1990.

Dead 1993.

#### **Collision Details**

**Date:** 06-May-1960

Visibility (nautical miles): Air Temperature:

Visibility: Unknown WaterTemperature:

Visibility - Fog:UnknownWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Unknown Sea State: Unknown

Collision Speed:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canadä

# Ship-Iceberg Collision Incident Report



Page 2 of 3

# **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Large hole Size - Length (m): 3

Location: Bow Size - Height (m): 2.4

Code: Plate Damage Below WL (m):

Length of Downtime: 20 days estimated Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Struck an iceberg on the Grand Banks.

### **Damage Description:**

8' by 10' ( $2.4 \times 3$  m) hole in bow. The after tanks in the stern flooded so that the bow tanks could be pumped out. Estimated to take till May 26 to repair.

# Ice Details

Ice Briefing Received: Unknown

Iceberg Population: 23 IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve
A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canadä

# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: 46 ° 18 ′ 00 ″ N

Iceberg Size: Unknown Longitude: 052 ° 24 ′ 00 " W

Length: Date of Observation: 08-May-1960

Width:

Iceberg Tonnage:

### **Route Details**

Geographic Area: Grand Banks

Collision Latitude:  $46 \,\,^{\circ}\,\,04\,\,^{\prime}$  " N Collision Longitude:  $052\,\,^{\circ}\,\,25\,\,^{\prime}$  " W

Locale Accuracy: Estimated

Voyage:

Displacement:

Draft FWD (m): 8.53

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin:
Destination:

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

