

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name:	Reduta Ordona				Prime	Mover:	Diesel	
Flag:	Poland				Transr	nission:	Unknown	
ASPPR	Ice Class:	Туре D			Power	(kW):		8827
Lloyd's Class:		Unknown		# Prop	ellers:		1	
Baltic Class:		Unknown		Prop.	Туре:	Controllable Pitcl	h (CP)	
Vessel Type:		Bulk Carrier			Servic	e Speed:	16	
Owner:		Stern I	Form:					
Registered Country: Poland					Steel C	Grade:	Unknown	
Year of Manufacture: 1978				Miscellaneous Vessel Notes:				
Bow Shape: Bulbous							eliks Dzierzynski	", renamed 1990.
Stem Angle:						Engine: S Ice Stren	Sulzer 2 SA 6-cyl gthened	
Dimensions (m): Mass (tonnes):								
Leng	jth:	198.2	Gross:	20308				
Bean	n:	24.4	Net:	13145				
Dept	h:	11	Dead:	33490				

Collision Details

Date: 21-Jul-1996			
Visibility (nautical miles):		Air Temperature: 4	
Visibility: Poor		WaterTemperature: 3	
Visibility - Fog: Fog		Wind Speed: 3	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Daylight		Sea State: Calm	
Collision Speed:			
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :				
Scenario: Unknown	Steel Failure Type: Unknown				
Severity: Large hole	Size - Length (m):				
Location: Shoulder	Size - Height (m):				
Code: Hole	Damage Below WL (m):				
Length of Downtime: 4-5 weeks	Damage Above WL - Height (m):				
Cost of Downtime:	Damage Above WL - Length (m):				
Cost to Repair:					
No. Lives Lost: 0					
No. Injuries:	Cause of Deaths/Injuries: Unknown				
Cargo Loss: Unknown					
Pollution: Unknown	Pollution Potential: Unknown				

Cause of Damage:

Struck an iceberg, presumably a bergy bit or growler in fog and smooth seas in Hudson Strait, en route for Churchill, Manitoba.

Damage Description:

Hull damage to Nos. 1 & 2 holds. Arrived MIL Davie In, Lauzon for repairs July 31, then went to Halifax but dry-dock unavailable and returned to MIL September 3. Sailed for Churchill September 16.

IIP Iceberg Number:

Position of Nearest Known Iceberg:

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Bergy bit Length: Width: Iceberg Tonnage: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

Route Details

Geographic Area: Hudson Strait	Origin: Gdynia, Poland			
Collision Latitude: 61 ° 28 ′ 54 ″ N	Destination: Churchill, Manitoba			
Collision Longitude: 066 ° 38 ' "W	Distance:			
Locale Accuracy: Known	Cargo at Event:			
Voyage:				
Displacement:				
Draft FWD (m): 3.35				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

