

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Rose (III)			Prin	ne Mover:	Sail
Flag:			Trar	nsmission:	Unknown
ASPPR Ice Class:	Unknown		Pow	/er (kW):	
Lloyd's Class:	lass: Unknown		# Propellers:		
Baltic Class:	Unknown		Pro	p. Type:	Unknown
Vessel Type:	Sailing Vessel		Service Speed:		
Owner:		Stern Form:			
Registered Country:		Stee	el Grade:	Unknown	
Year of Manufacture:		Miscellaneous Vessel Notes:			
Bow Shape: Unknown			Barque.		
Stem Angle:					
<u>Dimensions (m):</u>	Mass	<u>(tonnes):</u>			
Length:		Gross:			
Beam:		Net:			
Depth:		Dead:			

Collision Details

Date: 05-Jul-1856			
Visibility (nautical miles):		Air Temperature:	
Visibility: Limited		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Night		Sea State: Unknown	
Collision Speed: Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5		Canadä
Fax:(709) 772-2462	Télécopieur:(709) 772-2462		

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :		
Scenario: Direct Impact	Steel Failure Type: Unknown		
Severity: Abandoned	Size - Length (m):		
Location: Bow	Size - Height (m):		
Code: Hole	Damage Below WL (m):		
Length of Downtime:	Damage Above WL - Height (m):		
Cost of Downtime:	Damage Above WL - Length (m):		
Cost to Repair:			
No. Lives Lost:			
No. Injuries:	Cause of Deaths/Injuries: Unknown		
Cargo Loss: Unknown			
Pollution: Unknown	Pollution Potential: Unknown		

Cause of Damage:

Ran into an iceberg stoving the bows to the foremast and filling immediately.

Damage Description:

Vessel being laden with timber did not sink and was found derelict by the "Hebe" July 15 and learned form a board fastened to the rigging that she had been struck by an iceberg ".. Staving in the starboard bow, taking away bowsprit and foretopmast, and ship making water fast, all hands employed at the pumps. Cew presumed lost.

In fact, crew was lifted on Julv 13 by Capt, Champion of the ship "Victoria". New York Times report gives a

IIP Iceberg Number:

Position of Nearest Known Iceberg:

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Unknown Length: Width: Page 3 of 3 Latitude: ° ' " N Longitude: ° ' " W

Date of Observation:

Route Details

Iceberg Tonnage:

Geographic Area: Grand Banks	Origin: Quebec			
Collision Latitude: 46 ° 30 ' " N	Destination: Plymouth			
Collision Longitude: 046 ° 50 ' "W	Distance:			
Locale Accuracy: Known	Cargo at Event: Timber			
Voyage:				
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

