



National Research  
Council  
Canada

Conseil National de  
Recherches  
Canada

Institute for Ocean  
Technology

Institut des Technologies  
Océaniques

## Ship-Iceberg Collision Incident Report



Page 1 of 3

### Vessel Characteristics

<b>Name:</b> Sea Voyager II	<b>Prime Mover:</b> Diesel
<b>Flag:</b> Canada	<b>Transmission:</b> Unknown
<b>ASPPR Ice Class:</b> Unknown	<b>Power (kW):</b>
<b>Lloyd's Class:</b> Unknown	<b># Propellers:</b> 1
<b>Baltic Class:</b> Unknown	<b>Prop. Type:</b> Fixed Pitch (FP)
<b>Vessel Type:</b> Fishing	<b>Service Speed:</b> 10
<b>Owner:</b>	<b>Stern Form:</b>
<b>Registered Country:</b>	<b>Steel Grade:</b> Unknown
<b>Year of Manufacture:</b> 1989	<b><u>Miscellaneous Vessel Notes:</u></b>
<b>Bow Shape:</b> Unknown	
<b>Stem Angle:</b>	
<b><u>Dimensions (m):</u></b>	<b><u>Mass (tonnes):</u></b>
<b>Length:</b> 19	<b>Gross:</b> 136
<b>Beam:</b> 7.6	<b>Net:</b> 66
<b>Depth:</b> 3.6	<b>Dead:</b>

### Collision Details

<b>Date:</b> 13-May-2000	<b>Air Temperature:</b>
<b>Visibility (nautical miles):</b>	<b>Water Temperature:</b>
<b>Visibility:</b> Unknown	<b>Wind Speed:</b>
<b>Visibility - Fog:</b> Unknown	<b>Wave Height:</b>
<b>Visibility - Snow:</b> Unknown	<b>Sea State:</b> Unknown
<b>Visibility - Light:</b> Unknown	
<b>Collision Speed:</b>	
Kerwin Place	Place Kerwin
P.O. Box 12093	C.P. 12093
St. John's, Newfoundland	St. John's, Terre-Neuve
A1B 3T5	A1B 3T5
Fax:(709) 772-2462	Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



## Damage Details

---

<b>Damage Sustained:</b> Yes	<b>Damage Report No. :</b>
<b>Scenario:</b> Striking concealed growler/ber	<b>Steel Failure Type:</b> Unknown
<b>Severity:</b> Hole	<b>Size - Length (m):</b>
<b>Location:</b> Unknown	<b>Size - Height (m):</b>
<b>Code:</b> Plate	<b>Damage Below WL (m):</b>
<b>Length of Downtime:</b>	<b>Damage Above WL - Height (m):</b>
<b>Cost of Downtime:</b>	<b>Damage Above WL - Length (m):</b>
<b>Cost to Repair:</b>	
<b>No. Lives Lost:</b>	
<b>No. Injuries:</b>	<b>Cause of Deaths/Injuries:</b> Unknown
<b>Cargo Loss:</b> Unknown	
<b>Pollution:</b> Unknown	<b>Pollution Potential:</b> Unknown

### Cause of Damage:

Struck ice 14 miles W of Cape Norman

### Damage Description:

Holed and took on water; contolled by pumps. Escorted to Port Saunders

## Ice Details

---

**Ice Briefing Received:** Unknown

**Iceberg Population:**

**IIP Iceberg Number:**

**Sea Ice Concentration:** 4

**Position of Nearest Known Iceberg:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown

Latitude: 0 ° ' " N

Iceberg Size: Unknown

Longitude: 0 ° ' " W

Length:

Date of Observation:

Width:

Iceberg Tonnage:

## Route Details

---

Geographic Area: Strait of Belle Isle and

Origin:

Collision Latitude: 51 ° 37 ' " N

Destination:

Collision Longitude: 056 ° 18 ' " W

Distance:

Locale Accuracy: Known

Cargo at Event:

Voyage:

Displacement:

Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

