National Research
Council
Canada

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Conseil National de

Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

Steel screw steamer.

## **Vessel Characteristics**

Name:SeirstadPrime Mover:SteamFlag:NorwayTransmission:Unknown

ASPPR Ice Class: Unknown Power (kW):
Lloyd's Class: Unknown # Propellers:

Baltic Class: Unknown Prop. Type: Unknown

 Vessel Type:
 Steamship
 Service Speed:

 Owner:
 Norway
 Stern Form:

Registered Country: 1921 Steel Grade: Unknown

Year of Manufacture: <u>Miscellaneous Vessel Notes:</u>

Bow Shape: Unknown

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

 Length:
 138.4
 Gross:
 6632

 Beam:
 14.9
 Net:

 Depth:
 8.45
 Dead:
 3753

### **Collision Details**

**Date:** 17-May-1933

Visibility (nautical miles):

Visibility: Limited

WaterTemperature:

WaterTemperature:

Visibility - Fog:UnknownWind Speed:Visibility - Snow:UnknownWaveHeight:

Visibility - Light: Night Sea State: Unknown

**Collision Speed:** 

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 2 of 3

## **Damage Details**

Damage Sustained: Yes Damage Report No. :

Scenario: Striking concealed growler/ber Steel Failure Type: Unknown

Severity: Sinking Size - Length (m):

Location: Unknown Size - Height (m):

Code: Hole Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Yes

Pollution: Unknown Pollution Potential: Unknown

#### Cause of Damage:

Struck a low lying growler off Cape St. Francis, NF at night in raging seas.

### **Damage Description:**

Pierced the bottom of the ship beneath the engine room (cut a gaping hole). Engine room water tight bulkhead let go and flooding caused an explosion in the engine room [perhaps explosion tore out bulkhead]. Sank. Crew in boats all night, safe.

### Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

**Iceberg Size:** Growler Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

**Route Details** 

Geographic Area: Grand Banks

Collision Latitude: 47 ° 48 ' " N

Collision Longitude: 052 ° 42 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

**Radar Details:** 

Origin: Wabana, Bell Island, NF

**Destination:** Rotterdam

Distance:

Cargo at Event: 11,950 tons of iron ore.

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

