National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report

1852

Page 1

Vessel Characteristics

Name: Speranza

Prime Mover: Sail

Transmission:

Flag:

Unknown

Lloyd's Class:

ASPPR Ice Class: Unknown Power (kW):

Unknown # Propellers:

Baltic Class:

Unknown Prop. Type: Unknown

Vessel Type:

Sailing Vessel

Owner: T.M. Nielson & Son

Service Speed:

Stern Form:

Registered Country: United Kingdom Steel Grade: Unknown

Year of Manufacture:

Miscellaneous Vessel Notes:

Bow Shape: Unknown Wooden Barque, regularly operating between

Stem Angle:

Liverpool and Canada.

Dimensions (m): Mass (tonnes):

Length: 34.5 Beam: 8.2 Depth: 5.1

Gross: Net: Dead:

354 241 326

Collision Details

Date: 10-Jul-1890

Visibility (nautical miles):

Fog

Night

Air Temperature:

Visibility: Poor

WaterTemperature:

Visibility - Fog:

Wind Speed: 25

Visibility - Snow: Unknown WaveHeight:

St. John's, Newfoundland

Sea State: Moderate

Visibility - Light: **Collision Speed:**

Kerwin Place P.O. Box 12093

Fax:(709) 772-2462

A1B 3T5

Place Kerwin C.P. 12093

St. John's, Terre-Neuve

A1B 3T5

Télécopieur:(709) 772-2462

Canada

Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Sinking Size - Length (m):

Location: Bow Size - Height (m):

Code: Hole Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 4

No. Injuries: 1 Cause of Deaths/Injuries: Unknown

Cargo Loss: Yes

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Ran into a berg without doing any great damage one day then two nights later in a thick fog and strong NW winds ran into a berg as high as the spars and fully a mile long off the Grand Banks. Lat - lon estimated.

Damage Description:

Bows crushed against cliff like face and vessel began to sink at once. Masts came down and vessel continued to crunch against side of berg. Crew took to two boats. Apparantly on east side of huge ice field. Started towards Newfoundland. Took 3 days to get through ice field and 1 boat with 4 men became separated in fog after second day and was never seen again. Low on provisions which ran out on eighth day were spotted by the bark Askow on the ninth and the 6 survivors including a boy with badly frozen feet were

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin PlacePlace KerwinP.O. Box 12093C.P. 12093St. John's, NewfoundlandSt. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Ice Island Longitude: ° ' " W

Length: 1600 Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: $46~^{\circ}~03~^{'}$ " N

Collision Longitude: 048 $^{\circ}$ 57 $^{'}$ " W

Locale Accuracy: Unknown

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Liverpool

Destination: Shediac, New Brunswick

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

