National Research Council

Council

Conseil National de Recherches

Canada

Institute for Ocean Technology

Institut des Technologies

ology Océaniques

Ship-Iceberg Collision Incident Report

NAC CNAC

Page 1 of 3

Vessel Characteristics

Name:TitanicPrime Mover:SteamFlag:UKTransmission:Unknown

ASPPR Ice Class: Unknown Power (kW): 41013

Lloyd's Class: Unknown # Propellers: 3

Air Temperature:

Baltic Class: Unknown Prop. Type: Screw Propeller

Vessel Type: Passenger Service Speed: 23

Owner: White Star Line Stern Form:

Registered Country: UK Steel Grade: Unknown

Year of Manufacture: 1912 <u>Miscellaneous Vessel Notes:</u>

Bow Shape: Unknown Sheer strake 1" + 1"

Stem Angle:

Waterline plate 1.0"
Turn of Bilge 1.0"
Bottom Plate 1.0".

Dimensions (m): Mass (tonnes):

 Length:
 259.8
 Gross:
 46328

 Beam:
 28.2
 Net:
 21831

Depth: 10.54 Dead:

Collision Details

Date: 14-Apr-1912
Visibility (nautical miles):

Visibility: Limited WaterTemperature:

Visibility - Fog:ClearWind Speed:Visibility - Snow:ClearWaveHeight:

Visibility - Light: Night Sea State: Unknown

Collision Speed: 22

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Glancing Blow Steel Failure Type: Brittle

Severity: Sinking Size - Length (m): 90

Location: Bow Size - Height (m):

Code: Plate Damage Below WL (m): 7.5

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 1503

No. Injuries: Cause of Deaths/Injuries: Fall to Deck

Cargo Loss: Yes

Pollution: No Pollution Potential: No

Cause of Damage:

Hit a berg at 11:40 pm in a clear night while attempting to avoid it at 22.5 knots trying to manoeuvre around berg and reversing engines.

Damage Description:

Sank in about 2½ hours from gashes in plating below waterline with huge loss of life. Gashes were 10' (3m) above the keel and intermittent for 300' (90m). Apparently some damage above waterline also. Survivors (703) in boats picked up by the "Carpathia"

Ice Details

Ice Briefing Received: Good Forewarning

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Medium Longitude: ° ' " W

Length: 100 Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: 41 ° 56 ' " N

Collision Longitude: 050 ° 14 ' " W

Locale Accuracy: Known

Voyage:

Displacement: 54000

Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Southampton

Destination: New York

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

