National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report

147.6

2

Page 1

Vessel Characteristics

Name: Unacana USA

Lloyd's Class:

Baltic Class:

Flag:

ASPPR Ice Class: Unknown

Unknown

Unknown

Steamship **Vessel Type:** Owner: Santa Maria Steamship Company Ltd.

Registered Country:

United Kingdom

10.2

4.2

Year of Manufacture: 1927

Bow Shape: Unknown

Stem Angle:

Dimensions (m):

Length:

Beam: Depth:

Mass (tonnes): 63.2 Gross:

Net:

Dead:

Prime Mover: Steam

Transmission: Unknown

Power (kW): # Propellers:

Prop. Type: Unknown

Service Speed:

Stern Form:

Steel Grade: Unknown **Miscellaneous Vessel Notes:**

Steam twin screw.

Collision Details

Date: 23-Oct-1929

Visibility (nautical miles):

Visibility: Unknown Visibility - Fog: Unknown

Visibility - Snow: Unknown

Visibility - Light: **Collision Speed:**

Kerwin Place

Unknown

P.O. Box 12093 St. John's, Newfoundland

A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve

A1B 3T5 Télécopieur:(709) 772-2462 Air Temperature:

WaterTemperature:

Wind Speed:

944

485

783

WaveHeight:

Sea State: Unknown



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Report No. : Damage Sustained: Yes

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Denting Size - Length (m): Location: Bow Size - Height (m):

Code: Plate Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m): Damage Above WL - Length (m): **Cost of Downtime:**

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Hit ice 3 miles from Midway Light, Stephen's Passage, Alaska

Damage Description:

2 plates set up and several rivets loosened.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093 St. John's, Terre-Neuve St. John's, Newfoundland A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Alaskan Waters

Collision Latitude: $57~^{\circ}~30~'~$ " N

Collision Longitude: 133 ° 48 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Brait i ivb (iii).

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Ketchikan

Destination: Juneau

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

