

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

# Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

Name: Huntcliff		Prime Mover: Sail
Flag:		Transmission: Unknown
ASPPR Ice Class:	Unknown	Power (kW):
Lloyd's Class:	Unknown	# Propellers:
Baltic Class:	Unknown	Prop. Type: Unknown
Vessel Type:	Sailing Vessel	Service Speed:
Owner: M. Wood & Company		Stern Form:
Registered Country	y: United Kingdom	Steel Grade: Unknown
Year of Manufactur	re: 1824	Miscellaneous Vessel Notes:
Bow Shape: Unknown		Brig. Listed by Lloyd's Register as being a
Stem Angle:		snow.
<u>Dimensions (m):</u> Length: Beam: Depth:	<u>Mass (tonnes):</u> Gross: Net: Dead:	238

## **Collision Details**

Date: 17-May-1845			
Visibility (nautical miles):		Air Temperature:	
Visibility: Unknown		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Unknown		Sea State: Unknown	
Collision Speed:			
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

## Ship-Iceberg Collision Incident Report



## **Damage Details**

Damage Sustained: Yes	Damage Report No. :			
Scenario: Direct Impact	Steel Failure Type: Unknown			
Severity: Crushed	Size - Length (m):			
Location: Bow	Size - Height (m):			
Code: Frame	Damage Below WL (m):			
Length of Downtime:	Damage Above WL - Height (m):			
Cost of Downtime:	Damage Above WL - Length (m):			
Cost to Repair:				
No. Lives Lost:				
No. Injuries:	Cause of Deaths/Injuries: Unknown			
Cargo Loss: Unknown Pollution: Unknown	Pollution Potential: Unknown			

#### Cause of Damage:

Hit a berg on the Grand Banks.

#### **Damage Description:**

Bows stove. Next day lifted the crew off the Barque "Hope" sinking from damage by ice. Quebec Gazette #6357 09/06/1845 Page 3, Col. 1C: Captain Pearson, of the brig Huntcliff, arrived yesterday, reports that he came in contact with an iceberg on the 17th May, which stove in his bows, and caused the ship to make a great deal of water. On the 18th. he fell in with the bark Hope. Captain White. water-logged. and took off the crew. 11 in

### **Ice Details**

Ice Briefing Received: Unknown

**Iceberg Population:** 

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



IIP Iceberg Number:

Position of Nearest Known Iceberg:

# Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Unknown Length: Width: Iceberg Tonnage: Page 3 of 3 ° ' " N

Longitude: ° ' " W

Date of Observation:

Latitude:

## **Route Details**

Geographic Area: Grand Banks	Origin:			
Collision Latitude: 45 ° 28 ' " N	Destination:			
Collision Longitude: 048 ° 00 ' "W	Distance:			
Locale Accuracy: Unknown	Cargo at Event:			
Voyage:				
Displacement:				
Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

