

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

## Ship-Iceberg Collision Incident Report



Page 1 of 3

## **Vessel Characteristics**

Name: Lady Hobart		Prime Mover: Sail
Flag: UK		Transmission: Unknown
ASPPR Ice Class:	Unknown	Power (kW):
Lloyd's Class:	Unknown	# Propellers:
Baltic Class:	Unknown	Prop. Type: Unknown
Vessel Type:	Sailing Vessel	Service Speed:
Owner:		Stern Form:
Registered Country: UK		Steel Grade: Unknown
Year of Manufactur	r <b>e</b> : 1799	Miscellaneous Vessel Notes:
Bow Shape: Unknown		Falmouth Post Office Packet ship. Captain
Stem Angle:		William D. Fellowes.
Dimensions (m): Length: Beam: Depth:	<u>Mass (tonnes):</u> Gross: 17 Net: Dead:	179

## **Collision Details**

Date: 28-Jun-1803			
Visibility (nautical miles):		Air Temperature:	
Visibility: Poor		WaterTemperature:	
Visibility - Fog: Thick fog		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Night		Sea State: Unknown	
Collision Speed: Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Faw(700) 772 2462	6 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5		Canadä
Fax:(709) 772-2462	Télécopieur:(709) 772-2462		

Ship-Iceberg Collision Incident Report



## **Damage Details**

Damage Sustained: Yes	Damage Report No. :			
Scenario: Direct Impact	Steel Failure Type: Unknown			
Severity: Sinking	Size - Length (m):			
Location: Hulls	Size - Height (m):			
Code: Hole	Damage Below WL (m):			
Length of Downtime:	Damage Above WL - Height (m):			
Cost of Downtime:	Damage Above WL - Length (m):			
Cost to Repair:				
No. Lives Lost: 1				
No. Injuries: 26	Cause of Deaths/Injuries: Hypothermia/frostbite			
Cargo Loss: Unknown				
Pollution: Unknown	Pollution Potential: Unknown			

#### Cause of Damage:

Struck an island of ice,  $\frac{1}{4} - \frac{1}{2}$  mile (400 - 800 m) long and twice as high as the masthead, at 1 a.m. at 7 mph in intervals of thick fog about 350 miles (560 km) from St. John's, then struck again bringing helm round.

Northern Shipwreck Database places incident further west; 51W.

#### Damage Description:

Holed, then struck again against the chest-tree and swinging round the stern post being stove in and the rudder carried away. 27 persons including crew, passengers, captured French Captain and some of his men, escaped in two boats while ship sank almost immediately. Made Conception Bay July 4 (7 days) before being picked up minus the French captain who had previously thrown himself overboard in a delirious state (or was he eaten?). Crew frostbitten.

**IIP Iceberg Number:** 

Position of Nearest Known Iceberg:

### **Ice Details**

Ice Briefing Received: Unknown

**Iceberg Population:** 

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Large Length: 600 Width: Iceberg Tonnage: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

## **Route Details**

Geographic Area: Grand Banks	Origin: Halifax			
Collision Latitude: 46 ° 33 ' " N	Destination: Falmouth or Liverpool			
Collision Longitude: 044 ° 25 ' " W	Distance:			
Locale Accuracy: Known	Cargo at Event:			
Voyage:				
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

