



National Research  
Council  
Canada

Conseil National de  
Recherches  
Canada

Institute for Ocean  
Technology

Institut des Technologies  
Océaniques

## Ship-Iceberg Collision Incident Report



Page 1 of 3

### Vessel Characteristics

<b>Name:</b> Surinam	<b>Prime Mover:</b> Sail
<b>Flag:</b>	<b>Transmission:</b> Unknown
<b>ASPPR Ice Class:</b> Unknown	<b>Power (kW):</b>
<b>Lloyd's Class:</b> Unknown	<b># Propellers:</b>
<b>Baltic Class:</b> Unknown	<b>Prop. Type:</b> Unknown
<b>Vessel Type:</b> Sailing Vessel	<b>Service Speed:</b>
<b>Owner:</b> W. Miller	<b>Stern Form:</b>
<b>Registered Country:</b> Canada	<b>Steel Grade:</b> Unknown
<b>Year of Manufacture:</b> 1847	<b>Miscellaneous Vessel Notes:</b>

**Bow Shape:** Unknown  
**Stem Angle:**

<u>Dimensions (m):</u>		<u>Mass (tonnes):</u>	
<b>Length:</b>	30.9	<b>Gross:</b>	312
<b>Beam:</b>	7.1	<b>Net:</b>	0
<b>Depth:</b>	5.1	<b>Dead:</b>	

Ship. Listed by Lloyd's Register as a bark.

### Collision Details

<b>Date:</b> 30-Sep-1862	<b>Air Temperature:</b>
<b>Visibility (nautical miles):</b>	<b>Water Temperature:</b>
<b>Visibility:</b> Unknown	<b>Wind Speed:</b>
<b>Visibility - Fog:</b> Unknown	<b>Wave Height:</b>
<b>Visibility - Snow:</b> Unknown	<b>Sea State:</b> Unknown
<b>Visibility - Light:</b> Unknown	

**Collision Speed:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462



## Damage Details

---

<b>Damage Sustained:</b> Yes	<b>Damage Report No. :</b>
<b>Scenario:</b> Unknown	<b>Steel Failure Type:</b> Unknown
<b>Severity:</b> Sinking	<b>Size - Length (m):</b>
<b>Location:</b> Unknown	<b>Size - Height (m):</b>
<b>Code:</b> Hole	<b>Damage Below WL (m):</b>
<b>Length of Downtime:</b>	<b>Damage Above WL - Height (m):</b>
<b>Cost of Downtime:</b>	<b>Damage Above WL - Length (m):</b>
<b>Cost to Repair:</b>	
<b>No. Lives Lost:</b>	
<b>No. Injuries:</b>	<b>Cause of Deaths/Injuries:</b> Unknown
<b>Cargo Loss:</b> Unknown	
<b>Pollution:</b> Unknown	<b>Pollution Potential:</b> Unknown

### Cause of Damage:

Hit a berg in the Strait of Belle Isle. Lat - lon estimated.

### Damage Description:

Sank shortly after. Crew saved.

## Ice Details

---

**Ice Briefing Received:** Unknown

**Iceberg Population:**

**IIP Iceberg Number:**

**Sea Ice Concentration:**

**Position of Nearest Known Iceberg:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462



# Ship-Iceberg Collision Incident Report



Page 3 of 3

**Iceberg Shape:** Unknown

**Latitude:** 0 ° ' " N

**Iceberg Size:** Unknown

**Longitude:** 0 ° ' " W

**Length:**

**Date of Observation:**

**Width:**

**Iceberg Tonnage:**

## Route Details

---

**Geographic Area:** Strait of Belle Isle and

**Origin:** Greenock

**Collision Latitude:** 51 ° 33 ' " N

**Destination:** Montreal

**Collision Longitude:** 052 ° 28 ' " W

**Distance:**

**Locale Accuracy:** Estimated

**Cargo at Event:**

**Voyage:**

**Displacement:**

**Draft FWD (m):**

**Captain's Experience:** Unknown

**Radar Equipped?:** Unknown

**Radar Details:**

Kerwin Place  
P.O. Box 12093  
St. John's, Newfoundland  
A1B 3T5  
Fax:(709) 772-2462

Place Kerwin  
C.P. 12093  
St. John's, Terre-Neuve  
A1B 3T5  
Télécopieur:(709) 772-2462

