



National Research
Council
Canada

Conseil National de
Recherches
Canada

Institute for Ocean
Technology

Institut des Technologies
Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Colonel Burnaby	Prime Mover: Sail
Flag:	Transmission: Unknown
ASPPR Ice Class: Unknown	Power (kW):
Lloyd's Class: Unknown	# Propellers:
Baltic Class: Unknown	Prop. Type: Unknown
Vessel Type: Sailing Vessel	Service Speed:
Owner: H.B. Matthews	Stern Form:
Registered Country: United Kingdom	Steel Grade: Unknown
Year of Manufacture: 1886	<u>Miscellaneous Vessel Notes:</u>
Bow Shape: Unknown	Wooden Ketch.
Stem Angle:	
<u>Dimensions (m):</u>	<u>Mass (tonnes):</u>
Length: 24.5	Gross: 92
Beam: 6.3	Net: 72
Depth: 3.2	Dead: 92

Collision Details

Date: 01-Mar-1903	Air Temperature:
Visibility (nautical miles):	Water Temperature:
Visibility: Unknown	Wind Speed:
Visibility - Fog: Unknown	Wave Height:
Visibility - Snow: Unknown	Sea State: Unknown
Visibility - Light: Unknown	
Collision Speed:	
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :
Scenario: Unknown	Steel Failure Type: Unknown
Severity: Minor Deck Damage	Size - Length (m):
Location: Unknown	Size - Height (m):
Code: Unknown	Damage Below WL (m):
Length of Downtime:	Damage Above WL - Height (m):
Cost of Downtime:	Damage Above WL - Length (m):
Cost to Repair:	
No. Lives Lost:	
No. Injuries:	Cause of Deaths/Injuries: Unknown
Cargo Loss: No	
Pollution: No	Pollution Potential: No

Cause of Damage:

Collided with an iceberg. Lat - lon estimated.

Damage Description:

Deck damaged. Arrived St. John's April 3.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

IIP Iceberg Number:

Sea Ice Concentration:

Position of Nearest Known Iceberg:

Kerwin Place
P.O. Box 12093
St. John's, Newfoundland
A1B 3T5
Fax:(709) 772-2462

Place Kerwin
C.P. 12093
St. John's, Terre-Neuve
A1B 3T5
Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown

Latitude: 0 ' " N

Iceberg Size: Unknown

Longitude: 0 ' " W

Length:

Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Origin: St. Michael's

Collision Latitude: 46 ° 05 ' " N

Destination: St. John's

Collision Longitude: 053 ° 03 ' " W

Distance:

Locale Accuracy: Unknown

Cargo at Event:

Voyage:

Displacement:

Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place
P.O. Box 12093
St. John's, Newfoundland
A1B 3T5
Fax:(709) 772-2462

Place Kerwin
C.P. 12093
St. John's, Terre-Neuve
A1B 3T5
Télécopieur:(709) 772-2462

