National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report

Page 1

Vessel Characteristics

Name: Princess Royal

Prime Mover:

Flag:

Transmission:

Unknown

Sail

Lloyd's Class:

ASPPR Ice Class: Unknown Unknown Power (kW): # Propellers:

Baltic Class: Unknown Prop. Type:

Unknown

Vessel Type:

Sailing Vessel

Service Speed:

Owner: Bennett Smith

Stern Form:

Registered Country: Canada Steel Grade: Unknown

Year of Manufacture:

Miscellaneous Vessel Notes:

Bow Shape: Unknown Ship. Built in Windsor, Nova Scotia.

Stem Angle:

Dimensions (m):

Mass (tonnes):

1858

54.9

6.7

Gross: 959

Length: Beam:

11

880

Depth:

Net: Dead:

Collision Details

Date: 01-May-1863

Visibility: Unknown

Visibility (nautical miles):

Air Temperature:

WaterTemperature:

Visibility - Fog: Unknown Wind Speed:

Visibility - Snow: Unknown WaveHeight:

Visibility - Light: Unknown

St. John's, Newfoundland

Sea State: Unknown

Collision Speed:

Kerwin Place P.O. Box 12093

Fax:(709) 772-2462

A1B 3T5

Place Kerwin C.P. 12093

St. John's, Terre-Neuve

A1B 3T5

Télécopieur:(709) 772-2462

Canada

Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Unknown Steel Failure Type: Unknown

Severity: Sinking Size - Length (m):

Location: Unknown Size - Height (m):

Code: Hole Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Struck a berg off Newfoundland.

Damage Description:

Vessel abandoned and sank within 20 minutes. Crew saved by SS "Union".

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: $43 \, ^{\circ} \, 30 \, ' \, N$

Collision Longitude: 047 ° 10 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Liverpool

Destination: Halifax

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

