

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Ranzani			Pri	ne Mover:	Steam	
Flag:			Tra	nsmission:	Unknown	
ASPPR Ice Class:	Unknown			ver (kW):	0	104
Add i the diass.	Onknown		10			104
Lloyd's Class:	1A		# P	ropellers:		
Baltic Class:	Unknown		Pro	р. Туре:	Unknown	
Vessel Type:	Steamship		Ser	vice Speed:		
Owner: Stephens & Mawsen			Ste	rn Form:		
Registered Country	y: United King	gdom	Ste	el Grade:	Unknown	
Year of Manufactur	re: 18	379	<u>Mis</u>	cellaneous \	/essel Notes:	
Bow Shape: Unk	nown			Iron screw	Schooner.	
Stem Angle:						
<u>Dimensions (m):</u>	Ma	i <u>ss (tonnes):</u>				
Length:	78.6	Gross:	1422			
Beam:	9.8	Net:	913			
Depth:	6.5	Dead:	1322			
•						

Collision Details

Date: 23-May-1881			
Visibility (nautical miles):		Air Temperature:	
Visibility: Unknown		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Unknown		Sea State: Unknown	
Collision Speed: Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :		
Scenario: Unknown	Steel Failure Type: Unknown		
Severity: Unknown	Size - Length (m):		
Location: Unknown	Size - Height (m):		
Code: Unknown	Damage Below WL (m):		
Length of Downtime:	Damage Above WL - Height (m):		
Cost of Downtime:	Damage Above WL - Length (m):		
Cost to Repair:			
No. Lives Lost:			
No. Injuries:	Cause of Deaths/Injuries: Unknown		
Cargo Loss: Unknown Pollution: Unknown	Pollution Potential: Unknown		

Cause of Damage:

Struck an iceberg off Fogo Island.

Damage Description:

Damage to bows and forward compartment filled. Put into Betts Cove for repair.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

IIP Iceberg Number:

Position of Nearest Known Iceberg:



Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Unknown Length: Width: Iceberg Tonnage: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

Route Details

Geographic Area: Strait of Belle Isle and	Origin: Twillingate			
Collision Latitude: 49 ° 45 ' " N	Destination: Liverpool			
Collision Longitude: 054 ° 10 ' " W	Distance:			
Locale Accuracy: Known	Cargo at Event: 1800 tons of copper ore,			
Voyage:				
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

