

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Resolven			Prime Mover: Sail
Flag: Canada			Transmission: Unknown
ASPPR Ice Class:	Unknown		Power (kW):
Lloyd's Class:	1A		# Propellers:
Baltic Class:	Unknown		Prop. Type: Unknown
Vessel Type:	Sailing Vessel		Service Speed:
Owner: Mrs. J. Griffiths			Stern Form:
Registered Country: Canada			Steel Grade: Unknown
Year of Manufactu	ire: 18	372	Miscellaneous Vessel Notes:
Bow Shape: Uni	known		Brig built in PEI. Captain John James.
Stem Angle:			Finally lost ashore in 1888.
Dimensions (m):	M	iss (tonnes):	
Length:	29.3	Gross:	151
Beam:	7.2	Net:	143
Depth:	3.4	Dead:	145

Collision Details

Date: 27-Aug-1884			
Visibility (nautical miles):		Air Temperature:	
Visibility: Unknown		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Unknown		Sea State: Unknown	
Collision Speed: Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5		Canada
Fax:(709) 772-2462	Télécopieur:(709) 772-2462		

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :		
Scenario: Direct Impact	Steel Failure Type: Unknown		
Severity: Abandoned	Size - Length (m):		
Location: Bow	Size - Height (m):		
Code: Appendage	Damage Below WL (m):		
Length of Downtime:	Damage Above WL - Height (m):		
Cost of Downtime:	Damage Above WL - Length (m):		
Cost to Repair:			
No. Lives Lost: 11			
No. Injuries:	Cause of Deaths/Injuries: Unknown		
Cargo Loss: Unknown			
Pollution: Unknown	Pollution Potential: Unknown		

Cause of Damage:

Assumed to have struck a nearby iceberg.

Damage Description:

The vessel was found two days later after sailing derelict and abandoned with small boat gone but sails still set and fire still burning in galley. Assumed to have been abandoned in great hurry after probably striking nearby iceberg, but no wreckage. [Capt.+] 6 crew and 3 [4?] passengers lost. Vessel found 30 miles of Catalina and was towed to Harbour Grace.

Twillingate Sun..:"Brig "Resolven" Abandoned and Towed into Harbor Grace (Special to the Evening Mercurv)

IIP Iceberg Number:

Position of Nearest Known Iceberg:

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Unknown Length: Width: Page 3 of 3
Latitude: ° ' " N
Longitude: ° ' " W

Date of Observation:

Route Details

Iceberg Tonnage:

Geographic Area: Grand Banks	Origin: Harbour Grace, Newfoundland			
Collision Latitude: 48 ° 30 ' " N	Destination: Snug Harbour, Labrador			
Collision Longitude: 053 ° 02 ' " W	Distance:			
Locale Accuracy: Estimated	Cargo at Event: Barrels of salt and herring.			
Voyage:				
Displacement:				
Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

