

Conseil National de Recherches Canada

Institute for Ocean Technology

Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Royalist		Prir	ne Mover:	Sail
Flag: UK		Tra	nsmission:	Unknown
ASPPR Ice Class:	Unknown	Pov	ver (kW):	
Lloyd's Class:	Unknown	# Pı	opellers:	
Baltic Class:	Unknown	Pro	р. Туре:	Unknown
Vessel Type:	Sailing Vessel	Service Speed:		
Owner:		Ste	Stern Form:	
Registered Country:		Ste	el Grade:	Unknown
Year of Manufacture:		<u>Mis</u>	Miscellaneous Vessel Notes:	
Bow Shape: Unknown			Hull whaling ship.	
Stem Angle:				
Dimensions (m):	Mass (tonnes):			
Length:	Gross:			
Beam:	Net:			
Depth:	Dead:			

Collision Details

Date: 15-Apr-1814			
Visibility (nautical miles):		Air Temperature:	
Visibility: Poor		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Snow		WaveHeight:	
Visibility - Light: Night		Sea State: Unknown	
Collision Speed:			
Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :	
Scenario: Unknown	Steel Failure Type: Unknown	
Severity: Sinking	Size - Length (m):	
Location: Unknown	Size - Height (m):	
Code: Unknown	Damage Below WL (m):	
Length of Downtime:	Damage Above WL - Height (m):	
Cost of Downtime:	Damage Above WL - Length (m):	
Cost to Repair:		
No. Lives Lost:		
No. Injuries:	Cause of Deaths/Injuries: Drowned	
Cargo Loss: Unknown		
Pollution: Unknown	Pollution Potential: Unknown	

Cause of Damage:

Presumed sunk by iceberg during storm during the Davis Straits whale fishery.

Damage Description:

"Two most fatal shipwrecks have occurred in the Davis' Straits fleet, within the last five years. The Royalist, Captain Edmonds, and the London, Captain Matthews, having been lost with all hands; the former among icebergs in 1814, and the latter, it is supposed, in a similar way, in 1817. Little is known respecting these distressing events, especially with regard to the London. As to the other ship, however, I have received a few particulars from an intelligent seaman. Captain Bennet of the Venerable, who was in company with the

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin

IIP Iceberg Number:

Position of Nearest Known Iceberg:



C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Unknown Length: Width: Iceberg Tonnage: Page 3 of 3 ° ' " N

Longitude: ° ' " W

Date of Observation:

Latitude:

Route Details

Geographic Area: Labrador Sea and Davi	Origin: Hull			
Collision Latitude: 61 ° 07 ' " N	Destination: Davis Strait			
Collision Longitude: 056 ° 13 ' " W	Distance:			
Locale Accuracy: Estimated	Cargo at Event:			
Voyage:				
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

