National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean

Institut des Technologies

Technology Océaniques

Ship-Iceberg Collision Incident Report



Page 1

Vessel Characteristics

Prime Mover: Name: Scotia Steam Flag: UK Transmission: Unknown

ASPPR Ice Class: Unknown Power (kW):

Lloyd's Class: Unknown # Propellers: 2

Baltic Class: Unknown Prop. Type: Unknown Steamship **Vessel Type:** Service Speed: 14

Owner: Telegraph Construction & Maintenance Company Stern Form:

Mass (tonnes):

Steel Grade: **Registered Country:** UK Unknown

Miscellaneous Vessel Notes: Year of Manufacture: 1862

Bow Shape: Unknown Originally a Blue-Riband Cunard paddle

wheeler, sold and converted to a cable laying Stem Angle: twin screw steamer in 1879.

Wrecked in 1904

Length: 115.63 Gross: 4667

Beam: 14.56 Net: Depth: 6.1 Dead:

Collision Details

Dimensions (m):

Date: 02-Jul-1894

Air Temperature: Visibility (nautical miles):

Visibility: Poor WaterTemperature:

Wind Speed: Visibility - Fog: Thick fog WaveHeight: Visibility - Snow: Unknown

Sea State: Unknown Visibility - Light: Unknown

Collision Speed: 3

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Terre-Neuve St. John's, Newfoundland

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur: (709) 772-2462



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Glancing Blow Steel Failure Type: Unknown

Severity: Cracks Size - Length (m):

Location: Bow Size - Height (m):

Code: Frame Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 1

No. Injuries: Cause of Deaths/Injuries: Illness

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Collided with an iceberg at 1 a.m. at 3 m.p.h. in dense fog. [discrepency between reported positions, one report saying 60 miles off Heart's Content, the other the reported position]

Damage Description:

Broke bow girders and proceeded to Heart's Content for repairs. 1 man died of heart attack. Harbour Grace Standard, July 9: "Arrival of The Cable Ships". The cable ships, having on board the 1894 cable, arrived in Heart's Content - the "Scotia" on Friday, the "Britannia" on Monday. The coal tender, the "Loughrigg Holme," also arrived on Monday morning. The Scotia is commanded by Capt. W.R. CATO; is 2.931 tons register: 368 feet long: 47 feet beam, and draws aft 28 feet. Her passengers and crew are

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canadä

Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Unknown Longitude: ° ' " W

Origin:

Destination:

Cargo at Event:

Distance:

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: 48 $^{\circ}$ 37 $^{\prime}$ " N

Collision Longitude: 049 ° 09 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place

P.O. Box 12093

St. John's, Newfoundland

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5

A1B 3T5 A1B 3T5 Fax:(709) 772-2462 Télécopieur:(709) 772-2462

