National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Tellus
Flag: Holland

ASPPR Ice Class: Unknown
Lloyd's Class: Unknown

Baltic Class: Unknown

Vessel Type: Freighter

Owner: KNSM

Registered Country:

Holland

Year of Manufacture: 1890

Bow Shape: Unknown

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

Length:

Beam: Depth: Prime Mover:

Transmission:

on: Unknown

Unknown

Steam

Power (kW):

Propellers:

Prop. Type:

Service Speed:

Stern Form:

4050

7395

Steel Grade: Unknown

Miscellaneous Vessel Notes:

Most likely vessel is this one. 1931 renamed Sebaa.

1942 renamed Forli 1943 torpedoed and sunk.

Collision Details

Date: 27-Apr-1914

Visibility (nautical miles):

Visibility: Unknown
Visibility - Fog: Unknown

Visibility - Snow: Unknown

Visibility - Light: Collision Speed:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland

St. John's, Newfoundland St A1B 3T5 A1

Unknown

Fax:(709) 772-2462

St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

Place Kerwin

C.P. 12093

Gross:

Net:

Dead:

Air Temperature:

WaterTemperature:

Wind Speed:

WaveHeight:

Sea State: Unknown



Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Grounding on Steel Failure Type: Unknown

Severity: Puncture Size - Length (m):

Location: Bow Size - Height (m):

Code: Plate Damage Below WL (m):

Length of Downtime:

Damage Above WL - Height (m):

Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost:

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Collided with a growler 160 miles off St. John's.

Damage Description:

Forepeak and bow damaged and a number of rivets were loosened causing her to leak. Next day hit again and 2 blades broken off propeller. Had to be dry-docked.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Page 3 of 3

Iceberg Shape: Unknown Latitude: ° ' " N

Iceberg Size: Growler Longitude: 0 " W

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: Grand Banks

Collision Latitude: 47 ° 37 ' " N

Collision Longitude: 048 ° 48 ' " W

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Origin: Rotterdam

Destination: St. John's

Distance:

Cargo at Event:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

