

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Bahia B	lanca		Prime Mover: Steam	
Flag: German	у		Transmission: Unknown	
ASPPR Ice Class	s: Unknown		Power (kW):	
Lloyd's Class:	Unknown		# Propellers:	
Baltic Class:	Unknown		Prop. Type: Unknown	
Vessel Type:	Freighter		Service Speed: 12	
Owner: Hamburg South America Line			Stern Form:	
Registered Cour	ntry: UK		Steel Grade: Unknown	
Year of Manufacture: 1918			Miscellaneous Vessel Notes:	
Bow Shape: U Stem Angle:	Jnknown		Built as "Celtic Prince" 1926 sold and renamed "Schonfels". Sold and renamed 1938.	
Dimensions (m)	<u>. Ma</u>	<u>iss (tonnes):</u>		
Length: Beam: Depth:	137 17.47	Gross: Net: Dead:	8558	

Collision Details

Date: 10-Jan-1940			
Visibility (nautical miles):		Air Temperature:	
Visibility: Unknown		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Unknown		Sea State: Unknown	
Collision Speed: Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadă

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :
Scenario: Unknown	Steel Failure Type: Unknown
Severity: Sinking	Size - Length (m):
Location: Unknown	Size - Height (m):
Code: Unknown	Damage Below WL (m):
Length of Downtime:	Damage Above WL - Height (m):
Cost of Downtime:	Damage Above WL - Length (m):
Cost to Repair:	
No. Lives Lost:	
No. Injuries:	Cause of Deaths/Injuries: Unknown
Cargo Loss: Unknown	
Pollution: Unknown	Pollution Potential: Unknown

Cause of Damage:

Hit an iceberg in Denmark Strait from Buenos Aires, or Rio de Janeiro to Germany 60 miles off Iceland.

Damage Description:

Sank next day. 62 crew members were rescued by Icelandic trawler Hafsteinn and brought to Reykjavik. One unconfirmed report stated that after striking the iceberg the ship was sunk next day by the RN cruiser Newcastle. Another report states that HMS Glasgow was shadowing her. Crew was later arrested when island was occupied by the British and sent to camps in Britain and Canada.

IIP Iceberg Number:

Position of Nearest Known Iceberg:

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Unknown Length: Width: Iceberg Tonnage: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

Route Details

Geographic Area: South Greenland Wate	Origin: Buenos Aires or Rio de Janeiro			
Collision Latitude: 67 ° 00 ' " N	Destination: Germany			
Collision Longitude: 023 ° 00 ' " W	Distance:			
Locale Accuracy: Estimated	Cargo at Event:			
Voyage:				
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

