National Research Council

Canada

Conseil National de

Recherches Canada

Institute for Ocean Technology

Institut des Technologies

Océaniques

Ship-Iceberg Collision Incident Report

NAC-CNAC

Page 1 of 3

Vessel Characteristics

Name: Dorothy Melita

Flag: Newfoundland

ASPPR Ice Class: Unknown
Lloyd's Class: Unknown

Baltic Class: Unknown

Vessel Type: Sailing Vessel

Owner: J.B. Patten & Sons Ltd.

Registered Country: Newfoundland

Year of Manufacture: 1916

Bow Shape: Unknown

Stem Angle:

<u>Dimensions (m):</u> <u>Mass (tonnes):</u>

Length: Gross: 95

Beam: Net: Depth: Dead:

Prime Mover: Unknown

Transmission: Unknown

Power (kW):

Propellers:

Prop. Type: Unknown

Service Speed:

Stern Form:

Air Temperature:

WaterTemperature:

Steel Grade: Unknown

Miscellaneous Vessel Notes:

Schooner out of Grand Bank.

Collision Details

Date: 28-May-1933

Visibility (nautical miles): 9
Visibility: Limited

Visibility - Fog: Unknown Wind Speed:
Visibility - Snow: Unknown WaveHeight:

 Visibility - Snow:
 Unknown
 WaveHeight:

 Visibility - Light:
 Night
 Sea State: Unknown

Collision Speed:

Kerwin Place Place Kerwin P.O. Box 12093 C.P. 12093

St. John's, Newfoundland St. John's, Terre-Neuve A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462

Canadä

Ship-Iceberg Collision Incident Report



Page 2 of 3

Damage Details

Damage Sustained: Yes Damage Report No. :

Scenario: Direct Impact Steel Failure Type: Unknown

Severity: Sinking Size - Length (m):

Location: Bow Size - Height (m):

Code: Hole Damage Below WL (m):

Length of Downtime: Damage Above WL - Height (m):

Cost of Downtime: Damage Above WL - Length (m):

Cost to Repair:

No. Lives Lost: 1

No. Injuries: Cause of Deaths/Injuries: Unknown

Cargo Loss: Unknown

Pollution: Unknown Pollution Potential: Unknown

Cause of Damage:

Hit a growler at 2 a.m. about 125 miles SE of Cape Spear.

Damage Description:

Maintopmast snapped off and person hit on head by iron. Supposedly not seriously injured bur records show that one man, Chesley Grandy died on May 30. Pumps manned for 2 days, abandoned 30th. Crew rowed to Cape Spear in a day and a night. 1 man out of the 23 lost.

Ice Details

Ice Briefing Received: Unknown

Iceberg Population: IIP Iceberg Number:

Sea Ice Concentration: Position of Nearest Known Iceberg:

Kerwin Place Place Kerwin
P.O. Box 12093 C.P. 12093
St. John's, Newfoundland St. John's, Terre-Neuve

A1B 3T5 A1B 3T5

Fax:(709) 772-2462 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



of 3 Page 3

" N Iceberg Shape: Latitude: Unknown

Iceberg Size: Growler Longitude: " W

Origin:

Destination:

Cargo at Event: 300 quintals of cod.

Distance:

Length: Date of Observation:

Width:

Iceberg Tonnage:

Route Details

Geographic Area: **Grand Banks**

46 0 01 ' " N **Collision Latitude:**

Collision Longitude: 050 ° 29 '

Locale Accuracy: Known

Voyage:

Displacement: Draft FWD (m):

Captain's Experience: Unknown

Radar Equipped?: Unknown

Radar Details:

Kerwin Place

A1B 3T5

P.O. Box 12093

Fax:(709) 772-2462

Place Kerwin C.P. 12093 St. John's, Terre-Neuve St. John's, Newfoundland A1B 3T5 Télécopieur:(709) 772-2462

Canada