

Conseil National de Recherches Canada

Institute for Ocean Technology Institut des Technologies Océaniques

Ship-Iceberg Collision Incident Report



Page 1 of 3

Vessel Characteristics

Name: Mary and Mildred			Prime Mover: Sail	
Flag: Newfound	lland		Transmission: Unknown	
ASPPR Ice Class:	Class: Unknown		Power (kW):	
Lloyd's Class:	Unknown		# Propellers:	
Baltic Class:	Unknown		Prop. Type: Unknown	
Vessel Type:	Sailing Vessel		Service Speed:	
Owner: F. Conrad			Stern Form:	
Registered Country: Canada			Steel Grade: Unknown	
Year of Manufacture: 1912			Miscellaneous Vessel Notes:	
Bow Shape: Unknown			Wooden Schooner. Called "Fearn's	
Stem Angle:			schoonee" in description.	
Dimonsions (m);	M	ass (tonnos):		
Dimensions (m):		ass (tonnes):		
Length:	32.5	Gross:	128	
Beam:	8	Net:	100	
Depth:	3.1	Dead:	115	

Collision Details

Date: 23-Apr-1917			
Visibility (nautical miles):		Air Temperature:	
Visibility: Limited		WaterTemperature:	
Visibility - Fog: Unknown		Wind Speed:	
Visibility - Snow: Unknown		WaveHeight:	
Visibility - Light: Night		Sea State: Unknown	
Collision Speed: Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462	Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462		Canadä

Ship-Iceberg Collision Incident Report



Damage Details

Damage Sustained: Yes	Damage Report No. :	
Scenario: Direct Impact	Steel Failure Type: Unknown	
Severity: Sinking	Size - Length (m):	
Location: Bow	Size - Height (m):	
Code: Hole	Damage Below WL (m):	
Length of Downtime:	Damage Above WL - Height (m):	
Cost of Downtime:	Damage Above WL - Length (m):	
Cost to Repair:		
No. Lives Lost:		
No. Injuries:	Cause of Deaths/Injuries: Unknown	
Cargo Loss: Unknown		
Pollution: Unknown	Pollution Potential: Unknown	

Cause of Damage:

Struck a growler in St. John's Narrows before daylight,

Damage Description:

Twillingate Sun: "Fearn's schooner Mary Mildred, from Cadiz, sank off Davey's wharf on Monday last. It appears that while making the Narrows, before daylight, she struck a submerged growler, below the water line. The schr. began to leak, but the crew managed to keep the water under control, and the Capt. managed to get her to port, and ran her aground in DAVEY's Cove. The schr. was made fast but, unfortunately, when the tide rose in the morning, the moorings parted, and she fell off in deep water and sank. An effort will be

Ice Details

Ice Briefing Received: Unknown

Iceberg Population:

Sea Ice Concentration:

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 IIP Iceberg Number:

Position of Nearest Known Iceberg:

Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462



Ship-Iceberg Collision Incident Report



Iceberg Shape: Unknown Iceberg Size: Growler Length: Width: Page 3 of 3 Latitude: ° ' " N

Longitude: ° ' " W

Date of Observation:

Route Details

Iceberg Tonnage:

Geographic Area: Grand Banks	Origin: Cadiz			
Collision Latitude: 47 ° 34 ' " N	Destination: St. John's			
Collision Longitude: 052 ° 41 ' " W	Distance:			
Locale Accuracy: Known	Cargo at Event:			
Voyage:				
Displacement: Draft FWD (m):				
Captain's Experience: Unknown				
Radar Equipped?: Unknown				
Radar Details:				

Kerwin Place P.O. Box 12093 St. John's, Newfoundland A1B 3T5 Fax:(709) 772-2462 Place Kerwin C.P. 12093 St. John's, Terre-Neuve A1B 3T5 Télécopieur:(709) 772-2462

